

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

L CONSERVATION DIVISIO
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1582	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company		8. Farm or Lease Name Lea 403 State
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 6
4. Location of Well UNIT LETTER B 660 North 1980 FEET FROM THE LINE AND FEET FROM THE East LINE, SECTION 17 TOWNSHIP 18S RANGE 35E NMPM.		10. Field and Pool, or Wildcat Undesignated Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3943' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & Abandoned in the following manner:

1. Set cmt retr @ 7737'.
2. Squeezed perms 7813-37' w/125 sx Cl C cmt. Spot cmt plug on top of retr 7637-7737'.
Displ hole w/10# brine mud.
3. Spot 100' cmt plug 3820-3920' w/5 sx Cl C cmt
4. Spot 100' cmt plug 1800-1900' w/5 sx Cl C cmt
5. Spot 10 sx Cl C cmt @ surf, cut off wellhead below GL. Install regulation dry hole marker,
Well P&A eff: 8/03/81, cleaned & levelled location for abandonment.

FINAL REPORT.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Dean For: J.W. Schmidt TITLE Dist. Drlg. Supt. DATE 8/04/81

APPROVED BY Eddie W. Dean TITLE OIL & GAS INSPECTOR DATE APR 23 1982
CONDITIONS OF APPROVAL, IF ANY: