

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1189-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSED OR COMPLETED WORK. IT IS FOR THE USE OF THE OPERATOR TO REPORT ON THE WELL. IT IS NOT TO BE USED FOR PROPOSED OR COMPLETED WORK. IT IS FOR THE USE OF THE OPERATOR TO REPORT ON THE WELL. IT IS NOT TO BE USED FOR PROPOSED OR COMPLETED WORK.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator TEXACO Inc. .	8. Field or Lease Name N.M. 'AC' St. NCT-1
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 8
4. Location of Well UNIT LETTER 0 1980 FEET FROM THE East LINE AND 330 FEET FROM THE South LINE, SECTION 2 TOWNSHIP 18-S RANGE 34-E NEARBY	10. Field and Part, or Well No. Vacuum Abo Reef
11. Elevation (Show whether DF, RT, GR, etc.) 4013' (DF)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMERCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE PULL LOGS.

1. Rigged up.
2. Set RBP @ 5600' & dump 1 sx. sand on plug.
3. Perforate 2-7/8" csg w/2 JS @ 4305'. Set cement retainer @ 4237'.
4. Squeeze perfs @ 4305' w/600 sx Class 'C' cement. Ran Temp. Survey. Top of cement @ 2500'. WOC. DOC & test. Tested OK. Pull RBP.
5. Set pkr @ 5500'. Acidize 2-7/8" csg perfs 8625-8909' w/5000 gals 20% LST-NE acid foamed w/1000 bbl. SC-F N₂ in 5 equal stages using 4 ball sealers between stages.
6. Install pumping equipment. Test and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. L. Chaff* TITLE **Asst. District Supt.** DATE **6-20-80**

APPROVED BY *Jerry Sexton* TITLE DATE *JUN 22 1980*

CONDITIONS OF APPROVAL: **Disposal**