

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER: <u>shut-in</u>	7. Unit Agreement Name
2. Name of Operator <u>CONOCO INC.</u>	8. Farm or Lease Name <u>Goodwin "30"</u>
3. Address of Operator <u>P. O. Box 460, Hobbs, N.M. 88240</u>	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>18S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat <u>Arkansas Junction SA</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① MIRU. POOH w/tbg & rods
- ② Spot 2sxs @ PBTD (5685') Est TOC @ 5665'. Spot 2/sx cmt plug from 4726'-4513' to isolate San Andres.
- ③ Spot ^{203x77in} 10sxs from 3150'-3250' to isolate 8 5/8" shoe. Spot ^{203x77in} 10sxs cmt from 2913'-2813' to isolate top of the Yates.
- ④ Spot ^{203x77in} 10sxs from 1506'-1606' to isolate top of the anhydrite. Perf @ 405' w/ 4 JSFF thru 5 1/2" & 8 5/8". Pump cmt thru both annuli and circ. to surface. Cement displaced to 305' inside 5 1/2" csg.
- ⑤ Spot 10 sxs from 100' to surface.
- ⑥ Cut off well head, install P & A marker and rig down.
- ⑦ A proposed P & A sketch is attached.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Administrative Supervisor DATE 12-4-86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY SECABOUE
CONDITIONS OF APPROVAL, IF ANY: SECABOUE

DATE DEC 8 1986
Nmoco-Hobbs(3) File