

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI
(Other Instructions
verse side)Form approved,
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-01135

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME PLAINS UNIT FED.
2. NAME OF OPERATOR Anoco Production Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR Box 63, Hobbs, N. M. 88240	9. WELL NO. 9
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1935 FNL x 1935 FNL Sec. 33 (UNIT F, SE 1/4 NW 1/4)	10. FIELD AND POOL, OR WILDCAT Lusk-DeLaHare
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3553' R. D. B.
	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA 33-19-32 NM.PM
	12. COUNTY OR PARISH LEA
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

after evaluating, no further possibilities, remedial or recompletion, exist. Propose to P & A as follows:

Spot 25 S x Cement plug from PBD-4815 to 4515. (PERFS 4790-4900)

Shoot & Pull 4 1/2" casing from free point by stretch method
Est 7000' @ 3500'

Spot 40 S4 Cement plug from 3080 to 2970' (To Cover TYATES)

Spot 1800' Cement plug from 2600' to 800' (7 7/8" CSA 2603') 2705'.

Spot 10 S4 plug @ surface & erect P & A marker.

All intervals filled w/ mud laden fluid

Final Cleanup shall be made & ground restored to contour.

TD- 5150' 10 3/4" CSA 823' Circ 4 1/2" CSA 5150' (TCMT 3500' Est)
PBD- 4815' 7 7/8" CSA 2603' "

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE JAN 10 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
JAN 22 1973ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

Orig. USGS- H
1-DIV
1-SUSP
1-PRI
1-MOBIL