

COPIES RECEIVED	
DISTRIBUTION	
T A F E	
E	
G.S.	
ND OFFICE	
ERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.		3a. Indicate Type of Lease State ☒ Fee ☐
		5. State Oil & Gas Lease No. B-1448
1. Indicate Type of Well OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name State Vacuum Unit
2. Name of Operator Atlantic Richfield Company		8. Field or Lease Name State Vacuum Unit
3. Address of Operator P. O. Box 1710, Hobbs, NM 88240		9. Well No. 1 13
4. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 17S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Vacuum Grayburg S.A.
11. Elevation (Show whether DF, RT, GR, etc.) 4075' GR		12. County Lea


Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ RE-DRILL OR ALTER CASING ☐ OTHER <u>Convert To WIW</u> ☒	PLUG AND ABANDON ☐ CHANGE PLANS ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOB ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

FD 4738'. Completed OH 4564-4738'. Propose to convert a producing oil well to a water injection well in the State Vacuum Unit Waterflood Project per OCC Order No. 5762 in the following manner:

1. Rig up, install BOP, POH w/completion assy.
2. Clean out w/foam unit to TD & run caliper log.
3. RIH w/270' of 3 1/2" OD-NU tbg F/liner 4738-4468' & cmt.
4. RIH w/locator for liner pkr on 5 1/2" OD 15.5# K-55 csg w/float collar looking up, set into liner pkr @ 1448'. Pressure Test.
5. Pull out of liner pkr @ 1448' & cmt 8 5/8" x 5 1/2" annulus w/150 sx C1 C cmt cont'g 4% gel & 100 sx C1 C cmt, locate back into liner pkr.
6. GIH w/bit & drill out to PBD. Pressure test liner w/1000# for 30 min.
7. Perforate San Andres 4660-4710'.
8. RIH w/tbg locator sub & seal assy on internally plastic-lined tbg. Load 5 1/2" x 2 3/8" annulus w/trtd fresh water. Pressure test annulus w/1000# & install pressure gauge.
9. Acidize perfs 4660-4710' w/2000 gals 15% HCL-NE acid. Install well head for water injection. Shut-in till water injection plant is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED  Jerry Sexton District 1, Supv.	TITLE District Drlg. Supervisor	DATE 11/18/76
SIGNED BY _____ CONDITIONS OF APPROVAL, IF ANY: _____	TITLE _____	DATE NOV 22 1976

RECEIVED

DEC 16 1976

OIL CONSERVATION COMM.
HOBBS, N. M.