

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. 3-1056
7. Unit Agreement Name -
8. Farm or Lease Name 4.4.0 St.
9. Well No. 5
10. Field and Pool, or Wildcat Vacuum Glorieta
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
(USE APPLICATION FOR PERMIT - M (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator TEXACO Inc.
3. Address of Operator P. O. BOX 728 - Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER 0 460 FEET FROM THE South LINE AND 2080 FEET FROM East THE LINE, SECTION 25 TOWNSHIP 17-S RANGE 34-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3097' (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER Additional Perfs. in Glorieta ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install COP.
2. Clean out.
3. Set CIBP in temporarily abandoned Blinebry String @ 5200' & dump 30' cement on top of plug. Set cement retainer in Glorieta String @ 6150'.
4. Squeeze Glorieta perforations 6161' - 6188' w/5000 gal. Injectrol 'C' & follow w/50 sx Class 'C' Cement.
5. Perforate 2 7/8" Glorieta csg w/2-JSPF @ 6030', 6064', 67', 75', 87', 90', & 6094'.
6. Set pkr. @ 6010'. Acidize perfs. 6030' - 6094' w/2000 gal. 15% LST NE Acid in 4 equal stages using 250# rock salt in brine between each stage. Flush w/35 bbls. 2 % KCL Water.
7. Perforate Glorieta String into Blinebry from 6090' - 6094'. Use Glorieta as vent string.
8. Run 2 1/16" tubing in abandoned Blinebry String.
9. Install pumping equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 4-10-78

APPROVED BY [Signature] TITLE Dist. 1, Supt. DATE 4-10-78

CONDITIONS OF APPROVAL, IF ANY