

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
6-155

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name --
2. Name of Operator Texaco Inc.	8. Farm or Lease Name N. M. '0' St. NCT-1
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 23
4. Location of Well UNIT LETTER 0 , 600 FEET FROM THE South LINE AND 1200 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 17-S RANGE 34-E NMPM. Vacuum Glorieta	10. Field and Pool, or Wildcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 3990' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>Repair Water Flow</u> <input checked="" type="checkbox"/>		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods & pump from Glorieta string. Install BOP. Pull tubing.
2. Set RBP in Glorieta string @ 5000'.
3. Set RBP @ 5000' in abandoned 2 7/8" csg. string & dump 20' sand on plug.
4. Perf. abandoned 2 7/8" csg. string & 8 5/8" csg. w/2-holes @ 1545'.
5. Cement 11 3/4" x 8 5/8" csg. annulus w/500 sx. class 'H' cement & circulate. Squeeze w/addl. 200 sx. class 'H' cement. WOC. Run temperature survey if cement fails to circulate. WOC a total of 18 hrs. DOC & test. Pull RBP from both strings.
6. Run production equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED TITLE Asst. Dist. Supt. DATE 1/21/81

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: