

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002520274
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-155-1
7. Lease Name or Unit Agreement Name	New Mexico "O" State NCT-1
8. Well No.	18
9. Pool name or Wildcat	+ Vacuum upper Vacuum Wolfcamp, Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Producing Inc.
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	4. Well Location Unit Letter <u>H</u> : <u>1880</u> Feet From The <u>North</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>17-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4005' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

02-07-90 thru 03-21-90

- 1) MIRU PU. POH w/rods on WC side. Installed BOP on Upper Penn.
- 2) Ran paraffin knife to 2000'. TIH w/2-5/16" shoe on 2-1/16" tbg to 682'. Would not go deeper. TOH. Ran paraffin knife to 2250'.
- 3) Ran Happy Tool to 1875' for 4 hours. Hot watered 2-7/8" csg. Ran tool to 3375'.
- 4) TIH w/2-5/16" shoe on 1-5/8" DP to 9579'. Jarred tbg loose. TOH w/1-5/8" DP.
- 5) TIH w/rods. TOH laying down rods. Dropped rods.
- 6) Fished rods - laying down.
- 7) TIH w/2-5/16" Kutrite shoe, 2-7/8" csg scraper, 65 jts 1-5/8" DP. Tag'd @ 8900'.
- 8) TIH w/tap. Tag'd fish @ 9584'. TOH. TIH w/tap #2. Tag'd @ 9594'.
- 9) TIH w/2-5/16" Kutrite shoe to 9584'. Cut 9584-9591'. TOH. TIH w/blk. TOH w/blk.
- 10) Ran caliper log.
- 11) TIH w/DP. TOH w/DP laying down. UNSUCCESSFUL WORKOVER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard DeSoto TITLE Engineer's Assistant DATE 04-30-90

TYPE OR PRINT NAME R. B. DeSoto TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY DAVID L. TON
DISTRICT OFFICIAL

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 2 1990