

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. Unknown 30-025-20722
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. A-1320

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name New Mexico "K" State
2. Name of Operator Exxon Corp.	8. Well No. 32
3. Address of Operator P. O. Box 1600, Midland, TX 79702	9. Pool name or Wildcat Vacuum Glorieta
4. Well Location Unit Letter M : 330 Feet From The S Line and 330 Feet From The West Line Section 28 Township 17S Range 35E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3947 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-4-90 Pumped 20 bbls Aquafix, 2 bbls FW spaces, 60 sx Class C cmt. Pmpd 60 sx cmt displaced w/ gel mud.
10-5-90 Plug set 5700 to 6148', 135 sx C Neat
10-6-90 Perf tbg @ 4380'.
10-8-90 Perf 2-3/8 tbg @ 4000', plug set 4000' to 4380', 5 sx Class C
10-9-90 Perf tbg @ 2750', plug set 2750 to 2300', 30 sx cmt. Cut off tbg @ 2400', plug 2000 to 24000', 30 sx cmt. To plug 1345 - 1645', 30 sx cmt. Lay dn tbg to 150', 10 sx cmt to surf
10-10-90 Cut off wellhead, weld on plate and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon B. Timlin TITLE Staff Office Assistant DATE 10-30-90
TYPE OR PRINT NAME Sharon B. Timlin 915-688-7509 TELEPHONE NO.

(This space for State Use)

APPROVED BY Kenny W. Hef OIL & GAS INSPECTOR DATE _____
CONDITIONS OF APPROVAL, IF ANY: