

JOE D. RAMEY

P. O. BOX 6016

HOBBS, NEW MEXICO 88241

September 12, 1986

Mr. R. L. Stamets  
New Mexico Oil Conservation Division  
P. O. Box 2088  
Santa Fe, New Mexico 79701

Dear Mr. Stamets:

One of the provisions of Division Order No. R-8301 required a cement bond log be run before commencing injection into the subject well.


This case was heard on August 6, 1986, and an expedited order was requested since the former disposal well had experienced mechanical difficulties. I checked with Mr. Stogner several times to determine if he had any problem with the case and what was causing the delay. At no time did he indicate he would write other than a standard disposal order.

Osborn has equipped the well and to be required to run a bond log at this time would involve considerable time and expense.

Therefore, as per our conversation in the Hobbs office this date, Osborn is requesting permission to waive the requirements of a bond log at this time. We agree with Mr. Sexton's suggestion that when the well will no longer accept water on a vacuum, we will run a tracer survey. If and when the tubing and packer is pulled from the well, Osborn will then run the required cement bond log.

Thank you for your assistance in this matter.

Yours very truly,

  
Joe D. Ramey

cc: Mr. Mike Stevenson  
Osborn Heirs Company  
P. O. Box 17986  
San Antonio, TX 78286