

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30103
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE
6. State Oil / Gas Lease No.	B-1565
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	253
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL GAS WELL OTHER

2. Name of Operator: TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator: 205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter C : 675 Feet From The NORTH Line and 1330 Feet From The WEST Line
Section 36 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.) 4018' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: RETURN TA'D WELL TO PRODUCTION <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/26/00: MIRU. NDWH. TIH W/BIT, DC'S & TBG. TAG UP @ 4210'. DISPL W/10# BRINE. TEST CSG TO 500 PSI. DRILL 20' CMT TO CIBP @ 4230'. DRILL CIBP @ 4230'. PUSH TO 4262'.

6/27/00: LOWER TBG & TAG @ 4712'. DRILL & PSH CIBP TO 4717'. TIH W/TBG OPEN ENDED TO 4298'. SPOT 7000# 20/40 SAND 4298-4717'. PULL TBG TO 2794'. TAG SAND @ 4426'.

6/28/00: TIH W/FRAC PKR, SN. TESET TO 8500#. SET PKR @ 4268'. LOAD & TEST BACKSIDE TO 500# 15 MIN-OK.

6/30/00: FRAC OPEN HOLE 4325-4426' W/69,000# 16/30 RESIN COATED SAND.

7/05/00: TBG ON VAC. C/O FRAC SAND TO 4320'. REL PKR.

7/06/00: TIH W/BIT, DC'S ON TBG. TAG SAND @ 4316'. C/O SAND TO 4426'. WASH OUT 20/40 SPOT SAND TO 4547'.

7/07/00: OPEN WELL & LOWER TOOLS TO 4547'. C/O SAND TO TD @ 4717'.

7/10/00: TIH W/MOTOR, SEAL, GAS SEPR, PUMP, TBG. MOTOR @ 4305'.

7/11/00: NDBOP. LAND TBG. NUWH. RIG DOWN.

7/13/00: ON 24 HR OPT. PUMPED 11 BO, 650 BW, & 12 MCF. FINAL REPORT

TD?

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant DATE 8/22/00

TYPE OR PRINT NAME J. Denise Leake Telephone No 397-0405

(This space for State Use)

APPROVED _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL IF ANY _____

DeSoto-Nichols 12-93 ver 1.0

RECEIVED
Hobbs
OCD
NOV 2000