

AUG 27 1992

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Harvey E. Yates Company

3. ADDRESS OF OPERATOR
P.O. Box 1933 Roswell, NM 88202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310/N + 990/E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| | | | |
|--------------------------|--------------------------|-----------------------|-------------------------------------|
| REQUEST FOR APPROVAL TO: | | SUBSEQUENT REPORT OF: | |
| TEST WATER SHUT-OFF | <input type="checkbox"/> | | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | | <input checked="" type="checkbox"/> |
| (other) | | | |

5. LEASE
NM-11118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
North Young 3 Federal

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
North Young Bone Spring

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
H-374-32

12. COUNTY OR PARISH
Lea

13. STATE
NM

14. API NO.
30-025-30784

15. ELEVATIONS (SHOW DF, KDB, AND WD)

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-11-92 Spot 50' cement on top of CIBP @ 4100'

8-11-92 Set CIBP @ 3800' - 50' cement on top

8-12-92 Spot 50 sxs @ 2550' - 2304' tagged

8-12-92 Spot 50 sxs @ 467' - 328' tagged

8-12-92 Spot 20 sxs @ 50' - surface

8-12-92 Install dry hole marker

Circulated 9.5 mud

Pulled 2500' of 5 1/2" casing.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jim Gunn TITLE Ret Eng DATE 8/27/92

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 9/16/92
CONDITIONS OF APPROVAL, IF ANY: