

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-31195

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-155

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
CENTRAL VACUUM UNIT

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
TEXACO EXPLORATION AND PRODUCTION INC.

8. Well No.
291

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

9. Pool name or Wildcat
VACUUM GRAYBURG SAN ANDRES

4. Well Location
Unit Letter N : 660 Feet From The SOUTH Line and 1330 Feet From The WEST Line
Section 36 Township 17-SOUTH Range 34-EAST NMPM LEA County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)
GR-3999', KB-4014'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>COMPLETING</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- CLEANED OUT CASING TO PBTD OF 4750'. ATLAS RAN GR-CBL-CCL FROM 4750' TO SURFACE.
- PERF W/2 JSPF: 4584-4597, 4601-4609, 4617-4624, 4634, 4644 & 4675. 62 HOLES. HALLIBURTON ACIDIZED W/3200 GAL 15% NEFE ON 07-13-91. SWABBED 0 BO & 155 BW IN 8 HOURS, 07-15-91.
- TIH & SET RBP @ 4570'. TESTED TO 3000#. PERF W/2 JSPF: 4456, 4464-4492, 4501-4518, 4528-4536 & 4560. 110 HOLES. HALLIBURTON ACIDIZED W/5600 GAL 15% NEFE ON 07-16-91. SWABBED 14 BO, 6 BLW & 182 BW IN 9 HRS, 07-18-91. TIH AND MOVED RBP TO 4432'. SET AND TESTED TO 3000#.
- PERF W/2 JSPF: 4301-4312, 4319-4327, 4330-4339, 4343, 4347 & 4412-4415. 66 HOLES. HALLIBURTON ACIDIZED W/3200 GAL 15% NEFE ON 07-20-91. SWABBED 40 BO, 55 BLW & 41 BW IN 8 HOURS ON 07-21-91.
- TIH AND REMOVED RBP. TIH WITH TUBING AND SUBMERSIBLE PUMP.
- PUMPED 24 HOURS ON POTENTIAL TEST 07-30-91. RECOVERED 120 BO, 1500 BW & 58 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham/cwH TITLE DRILLING OPERATIONS MANAGER DATE 07-31-91

TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

200 05 1991

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: