DISTRIBUTION  NTA FE  -E  S.G.S.  ND OFFICE  ERATOR	NEW MEXICO OIL CONSERVATION COM	Fort Sup C-1	n C-103
DISTRIBUTION  NTA FE  LE  G.G.S.  ND OFFICE	NEW MEXICO OIL CONSERVATION COM	Sup C•1	edes Old
NTA FE  LE  G.G.S.  ND OFFICE	NEW MEXICO OIL CONSERVATION COM	C-1	
.E s.g.s. ND OFFICE	NEW MEXICO OIL CONSERVATION COM		0 2 d C-103
ND OFFICE		M1331011	
ND OFFICE		5a. Indi	cate Type of 1
			le 📊
ERATOR			e Oil & Gas Lease No.
		`` <sup>†</sup>	
			5183 & 818k
SUNDRY	NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROP USE **APPLICATION	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFEREN N FOR PERMIT —** (FORM C-101) FOR SUCH PROPOSALS.)		
		1.,	Agreement Name
OIL GAS WELL WELL	OTHER- Water Injection Well	West	Pearl Queen Unit-
dame of Operator		8, Farr	n or Lease Name
Galf Oil Corporation			
ddress of Operator		9. Well	No.
Ross (70) Walthan Wass M			<b>28-10</b> C
Dex 670, Hobbs, New M	EXTGO	10. Fie	eld and Pool, or Wildcat
	de Mande 7	aga Baa	rl Queen
UNIT LETTER 19	FEET FROM THE LINE AND	980 FEET FROM	
THE LINE, SECTION	28 TOWNSHIP 19-8 RANGE	35-B NMPM.	
		<u> </u>	<i></i>
	15. Elevation (Show whether DF, RT, GR, etc.	) 12. Co	unty ()
	3719 G <sup>L</sup>	Le	
Check A	ppropriate Box To Indicate Nature of Noti	ce Report or Other Da	ta
NOTICE OF IN	~ ~	SUBSEQUENT REPO	
NOTICE OF IN	TENTION TO:	SOBSEQUENT REF	SKT OF.
		<u></u>	
RFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	늗	ALTERING CASING
MPORARILY ABANDON	COMMENCE DRILL	ING OPNS.	PLUG AND ABANDONMENT
LL OR ALTER CASING	CHANGE PLANS CASING TEST AND	CEMENT JOB	<del></del>
	CHANGE PLANS CASING TEST AND	CEMENT JQB	
OTHER	OTHER	CEMENT JQB	
OTHER	Injection OTHER		ad date of starting any propose
Convert to the term of the proposed or Completed Operator work) SEE RULE 1103.	Tnjestion  Trations (Clearly state all pertinent details, and give per	inent dates, including estimat	
Convert to Hater  Convert to Hater  Describe Proposed or Completed Operation  work) SEE RULE'1103.  1924' PB.  It is proposed to strings of 3-1/16" pl  Type "M.G-2" dual page approximately 1680'.  type A packer and set	Injection OTHER	inent dates, including estimate of the country of t	4924'. Run 2 and 1 Guiberson hal packer at and seal nipple in I short string