

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name East Pearl Queen
2. Name of Operator Shell Oil Company (Western Division)	8. Farm or Lease Name East Pearl Queen
3. Address of Operator P. O. Box 1509, Midland, Texas 79701	9. Well No. 21
4. Location of Well UNIT LETTER A 660 FEET FROM THE north LINE AND 660 FEET FROM THE east LINE, SECTION 28 TOWNSHIP 19-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Pearl Queen
15. Elevation (Show whether DF, RT, GR, etc.) 3748' DF	
12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

December 27, 1967 - Approximate date work to be performed.

1. Pull rods, pump and tubing.
2. String shoot interval 4677'-4873' with 1-100 and 1-300 GRN per foot string shot.
3. Treat via tubing as follows:
 - A. Pump 400 bbls. hot fresh water with I-5.
 - B. Pump 1000 gals. 15% Dolowash.
 - C. Drop 40 ball sealers.
 - D. Pump 400 bbls. hot fresh water with I-5.
 - E. Pump 1000 gals. 15% Dolowash.
 - F. Flush with water.
4. Run rods and pump and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. W. Harrison TITLE Staff Exploitation Engineer DATE December 27, 1967

APPROVED BY N. W. Harrison TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: