

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04054
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1431-3
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 9
8. Well No.	11
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION WELL	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>25</u> Township <u>19S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #911 (11-18-96 THRU 12-06-96)

MIRU TYLER WELL SVC. PRESS. CSG. TO 500# FOR 30 MINS. OK. INT. CSG. HAD 150# & BLED DWN. TO 0#. TOO MUCH GAS TO CUT WELLHEAD. INSTALL BOP. RU JARREL WIRELINE. RUN CBL/GR/VDL/CLL LOGS. 6-5/8" CSG. FREE BEHIND CSG. RUN PERF. GUN & SHOT 4 HOLES @ 2,500'. CIRC. HOLE DWN. 6-5/8" CSG. & OUT 8-5/8" CSG. @ 3 BBLs./MIN. & 0# PRESS. - 120 BBLs. TIH W/6-5/8" BAKER CMT. RETAINER ON 2-7/8" TBG. TO 2,401'. PUMP 10 BBLs. FW THRU RETAINER. SET RETAINER @ 2,401'. RU HALLIBURTON. PRESS. TBG. TO 2,500#. OK. CIRC. 20 BBLs. FW THRU RETAINER OUT 8-5/8" CSG. PUMP 200 SKS. CLASS 'C' NEAT W/2% CALCIUM CHLORIDE IN 47 BBLs. SLURRY @ 3 BPM & 350# PRESS. PUMP 200 SKS. CLASS 'C' NEAT IN 47 BBLs. SLURRY @ 3 BPM @ 440# TO 1,100# PRESS. SHUT IN @ 1,050# PRESS. & PULL OUT OF RETAINER. CIRC. 14 BBLs. TO PIT. RD HALLIBURTON.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 12/09/96
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY JOHN J. BROWN TITLE DEPUTY COMMISSIONER DATE DEC 18 1996

CONDITIONS OF APPROVAL, IF ANY:

JLBN