

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Benito Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-05650

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-3657

7. Lease Name or Unit Agreement Name

BLOCK 5

NORTH MONUMENT G/SA UNIT

8. Well No.

11

9. Pool name or Wildcat

EUNICE MONUMENT G/SA

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER ☐

2. Name of Operator

AMERADA HESS CORPORATION

3. Address of Operator

DRAWER D, MONUMENT, NM 88265

4. Well Location

Unit Letter K : 1980 Feet From The SOUTH Line and 1980 Feet From The WEST Line

Section 19 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

WELL OR ALTER CASING ☐

OTHER: REPAIR CSG. ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLAN TO MIRU PULLING UNIT AND TOH WITH RODS AND PUMP. REMOVE WELLHEAD, INSTALL BOP AND TOH LAYING DOWN 2-1/16" TBG. RELEASE MODEL R PKR. AND TOH. TIH WITH 6" BIT TO 3902' AND TOH. TIH WITH 7-7/8" UNDER REAMER AND UNDER REAM OH FROM 3902'-3787'. TIH WITH 1400' 5-1/2" FLUSH JOINT LINER AND CEMENT IN PLACE WITH CLASS C CEMENT WITH 1/4#/SKS. CELLOPHONE FLAKES. WOC. TIH WITH 4-3/4" BIT AND DRILL OUT CEMENT TO CSG. SHOE. PRESS. TEST CSG. TO 500# FOR 30 MIN. RUN NEUTRON LOG ACROSS G/SA ZONE AND PERF. ZONE WITH 2 SPF. ACIDIZE PERFS. WITH 3000 GAL. 15% HCL. SWAB LOAD. TIH WITH TBG. REMOVE BOP, INSTALL WELLHEAD AND TIH WITH PUMP AND RODS. RDP, CLEAN LOCATION AND RESUME PROD. WELL.

(PRIOR - PHILLIPS LAND OFFICE #1)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

R. L. Wheeler, Jr.

TITLE SUPRV. ADMIN. SERVC.

DATE 5/12/92

TYPE OR PRINT NAME

R. L. Wheeler, Jr.

TELEPHONE NO. 393-2144

This space for State Use)

Signed by  
Paul Kautz  
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 15 1992