Submit 3 Copies

State of New Mexico Energy nerals and Natural Resources Department

Form C-103 Revised 1-1-89

to Appropriate District Office

DISTRICT I P.O. Rox 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION WELL APPRO

P.O. BOX 1980, HODDE, NM 88240	2040 Pacheco St.		TWELLAN RO
DISTRICT II			30-C25-C5679
P.O. Drawer DD, Artesia, NM \$8210			5. inducate Type of Lease STATE X. FEE
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			
1000 RO BILLIS RU., ALEC, 1441 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICES	AND REPORTS ON WELL	.S	
(DO NOT USE THIS FORM FOR PROPOSA			7. Lease Name or Unit Agreement Name
	USE "APPLICATION FOR PER FOR SUCH PROPOSALS.)	VII I "	
1. Type of Well:		· · · · · · · · · · · · · · · · · · ·	Huston Comm.
MET AET X	OTHER		
2. Name of Operator			& Well No.
Mewbourne Oil Company			= 1
3. Address of Operator	Marria 003/0		9. Pool same or Windcat
P.O. Box 5270, Hobbs, New	Mexico 8c_4U		Eumont Tates 7 Rivers Queen
1	South	10	20
Unit Letter K : 1650 F	eet From The	Line and18	Fee From The West Line
Section 21 T	ownship 195 Ran	37E	Lea .
	10. Elevation (Show whether D	ζC	NMPM County
X/////////////////////////////////////	// <u>;</u>	, , , , , , , , , , , , , , , , , , , ,	<i>*////////////////////////////////////</i>
11. Check Appr	opriate Box to Indicate N	ature of Notice B	Report or Other Date
NOTICE OF INTENT	TON TO:		
NOTICE OF INTERV	- ION 10.	501	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS PLUG AND ABANDONMENT
PULL OR ALTER CASING		CARING TEST AND C	
CASING TEST AIRD CEMEAT JOB			EMENT JOB
OTHER: Stimulate Well	<u>x</u>	OTHER:	
12. Describe Proposed or Completed Operations (C	Tearly state all newment details and	aina marinant dans in t	
work) SEE RULE 1103.	searly same on personal denois, and	give periment dates, incit	saing estimated mase of marting any proposed
 MIRU well service rig. 			
2. TOOH with tbg.			
3. RIH w/ $3\frac{1}{2}$ " workstring a		3400'.	
4. Fracture treat formati	lon (3475' - 3800').		
5. TOOH with workstring.			
5. Took with workstring.			

- 6. TIH w/production tbg and pkr.
- 7. Put well on production.

I hereby certify that the information above is true and complete to the best of say knowledge and belief.				
GNATURE /// CF7000	mue Production Marager	DATE <u>8-19-96</u>		
ypeorprotname Erik L. Hoover		ТЕЈЕРНОНЕ NO 393—5905		
has space for State Use)		1		
A Company of the Comp		* (# * * 5)		
PPROVED BY	TITLE	DATE		

