

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-05735

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
B-1167-18

7. Lease Name or Unit Agreement Name  
NORTH MONUMENT G/SA UNIT  
BLK.11

8. Well No.

9

9. Pool name or Wildcat  
EUNICE MONUMENT G/SA

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P.O. DRAWER D, MONUMENT, NM 88265

4. Well Location  
Unit Letter I : 2280 Feet From The SOUTH Line and 990 Feet From The EAST Line  
Section 29 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

### 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: CONVERT TO INJECTION WELL. ☒

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1109

MIRU PULLING UNIT & REVERSE UNIT. ND WELLHEAD. TOH & LAY DWN. RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. TIH W/RBP & SET @ +/-500'. INSTALL NEW WELLHEAD EQUIPMENT. TIH W/TBG. & RETRIEVE RBP. TOH W/RBP. TIH W/BIT, D.C.'S & TBG. CLEAN OUT TO PBTD @ 3,924'. TOH W/BIT. TIH W/A SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/1,000 GALS. 15% NEFE DI HCL W/3% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. AT +/-3,750'. SWAB/FLOW BACK LOAD. OBTAIN SHUT-IN BOTTOMHOLE PRESS. BEFORE BEGINNING INJ. EVALUATE FOR SAN ANDRES COMMUNICATION. RU SCHLUMBERGER & LOG W/SNL/GR TOOLS. TIH W/4" CSG. GUN. PERF. 3,794'-3,832', 2 JSPF, 180 DEG. PHASED HEG CHARGES (38 GEET, 77 TOTAL HOLES). RD SCHLUMBERGER. TIH W/A SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL WITH 4,000 GALS.  
(CONTINUED ON PAGE 2)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 02-21-96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNATURE  
DISTRICT SUPERVISOR

APPROVED BY TERRY L. HARVEY TITLE SR. STAFF ASSISTANT DATE FEB 26 1996

CONDITIONS OF APPROVAL, IF ANY: