

DISTRICT I
P.O. Box 1580, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL APL NO.	30-025-05767
3. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 15
8. Well No.	1
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265	4. Well Location Unit Letter A : 660 Feet From The NORTH Line and 660 Feet From The EAST Line Section 31 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: Intent to convert to Injection Well. ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1501

Move in and rig up pulling unit and reverse unit. TOH with rods and pump. Nipple down wellhead. Nipple up BOP. TOH with tubing laying down. Rig up Schlumberger and log the openhole with IDT/CNL/GR tools. Rig down Schlumberger. TIH with treating packer on tubing to +/- 3,700'. Load casing-tubing annulus with fresh water. Set packer. Rig up acid company. Acidize well with 5,000 gal. 15% NEFE DI HCL w/3% DP-77MX Micellar solvent (using rock salt as diverting agent as needed). Swab/flow back load. TOH w/tubing and packer, laying down production tubing. Pick up and TIH w/2 3/8" coated injection tubing w/injection packer. Nipple Down BOP. Nipple up injection wellhead assembly. Rig down and move out pulling unit. Clean and clear out location.

I hereby certify that the information shown is true and correct to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Staff Assistant DATE 10-24-94
TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 393-2144

(This space for State Use)

NOV 2 1994

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: