

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Blanco Rd., Aztec, NM 87410

WELL API NO. 3002505776
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	7. Lease Name or Unit Agreement Name J.R. PHILLIPS B.
2. Name of Operator AMERADA HESS CORPORATION	8. Well No. 4
3. Address of Operator DRAWER D, MONUMENT, NEW MEXICO 88265	9. Pool name or Wildcat EUNICE-MONUMENT G/SA
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>WEST</u> Line Section <u>31</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3616' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PULLING UNIT. RUN CEMENT BOND LOG AND COMPENSATED NEUTRON LOG FROM 3920'± - 2920'±. SET CIBP AT 3820'±. PERFORATE 7" CASING WITH 4" CASING GUN, LOADED WITH 4 JSPF FROM 3794' - 3804' FOR A TOTAL OF 40 SHOTS. ACIDIZE PERFORATIONS FROM 3794' - 3804' WITH 525 GALS. 15% NE-FE HCL. SWAB BACK LOAD AND EVALUATE PRODUCTION POTENTIAL. PERFORATE 7" CASING WITH A 4" CASING GUN, LOADED WITH 4 JSPF FROM 3764' - 3782', FOR A TOTAL OF 72 SHOTS. ACIDIZE PERFORATIONS FROM 3764' - 3782' WITH 1000 GALS. 15% NE-FE HCL. SWAB BACK LOAD AND EVALUATE PRODUCTION POTENTIAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eric Haas TITLE SR. PETROLEUM ENGR. DATE 6/21/91
TYPE OR PRINT NAME ERIC HAAS TELEPHONE NO. _____

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: