

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name G. C. Matthews
3. Address of Operator Box 670, Hobbs, New Mexico 88240	9. Well No. 8
4. Location of Well UNIT LETTER <u>0</u> , <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>20-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Monument Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3561' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

Plugged and Abandoned.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5720' TD.

Ran CI BP and set at 5600'. Loaded hole with abandonment mud containing 25# salt gel per barrel of water. Spotted 5 sack, 40' cement plug on top of BP at 5600' to 5560', 16 sack, 108' cement plug from 3931' to 3823', across top of 5-1/2" liner at 3887', 20 sack, 108' plug from 1134' to 1026', across top of salt and 10 sack plug from 54' to surface. Installed dry hole marker. Plugged and abandoned May 1, 1975. Will advise when location is ready for your inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Barba TITLE Area Engineer DATE May 1, 1975

APPROVED BY John W. Runyan TITLE _____ DATE _____

CONDITION OF APPROVAL, IF ANY: