

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002509880
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. 010972
7. Lease Name or Unit Agreement Name Keohane B.M. -A-
8. Well No. 1
9. Pool name or Wildcat Eunice Monument (G-SA) 23000

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Texaco E&P Inc.	
3. Address of Operator P.O. Box 3109, Midland, TX 79702 (915) 688-4816	
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>18</u> Township <u>19S</u> Range <u>37-E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify OCD 24hours before moving into P&A well.
2. MIRU Pool Well Service N.D. well head & N.U. BOP
3. Pickup tub & TIH tag cement plug @ 3586'. Mix & load hole w/9.5 mud.
4. Pull up hole to @ 2900'. Spot @ 80sx class C cement from 2900'-2600' Base of salt section.
5. Pull out hole w/tub. Rig up wireline & perf top of salt section @ 1700'. Rig down wireline.
6. TIH w/7" squeeze pkr. @ 1555 & sq w/100sx. cmt. displace cmt below pkr @ 1650' W.O.C. & tag.
7. TOH w/7" pkr. RUWL & perf 7" csq @ 1431'. RDWL truck. TIH w/7" pkr. to @ 1300'.
8. Pump 400 sx cmt & circ. cmt behind 7" csq to surface. Displace cmt below pkr. to @ 1310'. W.O.C. and tag.
9. TOH w/tub & pkr. TIH open ended w/tub to 190' Spot 50sx cmt plug from 190'-surface.
10. Laydown tub. Nipple down BOP. Cut off & cap well & weld 3" x 4' marker post w/legal

I hereby certify that the information above is true and complete to the best of my knowledge and belief. _____

SIGNATURE RJ Harding III TITLE Operations Engineer DATE 8-12-94

TYPE OR PRINT NAME RJ Harding III TELEPHONE NO. (915) 688-4816

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE AUG 17 1994

CONDITIONS OF APPROVAL, IF ANY:

SAD

RECEIVED

ALL INFORMATION

OUR RECORDS
OFFICE