NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION	•	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	C 10 11 mm	
U.S.G.S.	Ser 19 11 10 AM '85	5a. Indicate Type of Lease State Fee
LAND OFFICE		State State Oil & Gas Lease No.
OPERATOR		E = 3290
SUNDRY (DO NOT USE THIS FORM FOR PROP	NOTICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
USE "APPLICATIO	ON FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL GAS		,, с 13-55 144
Name of Operator	OTHER-	8. Farm or Lease Name
Skelly Oil Company		Mexico #Un
Address of Operator		9. Well No.
Box 730 - Hobbs, New	Mexico	2
Location of Well		10. Field and Pool, or Wildcat
G 16	50 North 1650	Hobbs
UNIT LETTER,	FEET FROM THE LINE AND FEET	FROM THITTING
Bast	8 19-S 38-E	
THELINE, SECTION	TOWNSHIP RANGE	- NMPM. ()
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3610' DF	Les
Chack A	ppropriate Box To Indicate Nature of Notice, Report	or Other Data
NOTICE OF IN	• • •	QUENT REPORT OF:
NOTICE OF IN	TENTION TO.	OENT NEI ONT OT.
ERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
ULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	TEGG AND ABANDONMENT
DEE ON ACTER CASING	OTHER	
OTHER		
ornex		
2. Pulled Rods & Tub 3. Cleaned Well out 4. Perforated 5-1/2" 5. Set retrieveable 6. Treated Through 5 7. Sumbbed & tested. 8. Pull Retrieveable 9. Treated thru performed 20000 lb 20/4 10. Pumped & tested was	With Send Pump. OD casing from 4079 - 4100° w/total of 6 shridge plug at 4005°. S-1/2° OD casing perfs. 4079 - 4100° w/100° shridge Plug at 4005°. S 4079 - 4100° & open hole section 4111 - 400 and. Call. lead oil well pumped 41 bbls new oil & 7° bil	00 gal 15% ME acid.
(ORIGINAL) H. E. A	above is true and complete to the best of my knowledge and belief. TITLE District Superintends	int date September 9, 196
SIGNED		

CONDITIONS OF APPROVAL, IF ANY: