

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI. DATE
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 43-21634

5. LEASE DESIGNATION AND SERIAL NO.

NM 0631

6. IF INDIAN, ALLOTTEE OR TRIBE LAND

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fed-Lea

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lea Bone Springs

11. SEC. T. R. M. OR S.W. AND
SURVEY OR AREA

11-20S-34E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)OIL WELL ☒ GAS WELL ☐ OTHER

1. NAME OF OPERATOR

Edwin Foster Blair

2. ADDRESS OF OPERATOR

c/o Hobbs Pipe & Supply P O Box 2010 Hobbs, N M

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1900' FSL & 2060' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether SP, ST, OR, etc.)

3653' KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETIONS

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Propose to spot 25 sx. cement plug from 10,000 to 10,300
2. Propose to spot a 25 sx. cement plug at top of bone spring at 8200' to 8300'.
3. Propose to spot a 25 sx. cement plug at 8 5/8" casing shoe at 5400' to 5500'.
4. Propose to spot a 25 sx. cement plug at 8 5/8" DV tool at 3600'-3700'.
5. Propose to spot a 25 sx. cement plug at top of salt at 1600'-1700'.
6. Propose to spot a 25 sx. cement plug at 13 3/8" casing shoe at 815'.
7. Hole will be loaded with mud laden fluids.
8. Propose to spot a 10 sx. cement plug at surface with marker.

4 1/2" casing to be cut and pulled from approximately 9,000 feet and
8-5/8" casing to be cut and pulled from approximately 2,500 feet.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

8-31-70

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

SEP 2 1970

ARTHUR R. BROWN
DISTRICT ENGINEER

*See instructions on reverse side