

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> d <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-8244

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Water Injection Well</b>	Jalmat	7. Unit Agreement Name	Field Yates Sand Unit
2. Name of Operator	Gulf Oil Corporation	8. Farm or Lease Name	
3. Address of Operator	Box 670, Hobbs, New Mexico 88240	9. Well No.	107
4. Location of Well	UNIT LETTER <u>B</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>22-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat	Jalmat
15. Elevation (Show whether DF, RT, GR, etc.)	3604' GL	12. County	Lea

## 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Plug and Abandon</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

## 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4010' TD, 4004' PB.

Pull injection equipment. Set CI BP at 3830' and cap with 5 sack cement plug to 3780'. Displace hole with water containing 25 sacks of gel per 100 barrel of water. Spot 15 sack cement plug from 2000' to 1850', across top of salt. Load hole with heavy mud. Spot cement plug from 50' to surface. Install dry hole marker and clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

## 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Barber TITLE Area Engineer DATE May 6, 1974

APPROVED BY Joe D. Raley TITLE Dist. J, Supv. DATE

CONDITIONS OF APPROVAL, IF ANY: