Office *	rico Form C-103
District I gy, Minerals and Natur	al Resources Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240	ELL API NO. 30-025-28925
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	DIVISION 5. Indicate Type of Lease
District III 1220 South St. France	cis Dr. STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	o. State On & Gas Lease 140.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	R SUCH N. Seven Rivers Queen Waterflood
PROPOSALS.)	14. Seven Rivers Queen Waterflood
1. Type of Well:	
Oil Well Gas Well Other Injector	8. Well No. 12
2. Name of Operator Chevron U.S.A. Inc	8. Well 140. 12
3. Address of Operator	9. Pool name or Wildcat
P. O. Box 1150, Midland, TX 79702	Eunice; Seven Rivers-Queen, South
4. Well Location	
Unit Letter O: 1305 feet from the South line and 2635 feet	from the East line
	NMDM County LEA
Section 4 Township 22S F  10. Elevation (Show whether DR	Range 36E NMPM County LEA
3584' GR	, KKB, KI, GK, etc.)
11. Check Appropriate Box to Indicate No.	ature of Notice Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK
PERFORM REMEDIAL WORK	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. PLUG AND
_	ABANDONMENT
PULL OR ALTER CASING   MULTIPLE	CASING TEST AND
COMPLETION	CEMENT JOB
OTHER:	OTHER:
(01 1 44 11 44	
12 Describe proposed or completed operations. (Clearly state all pett)	nent details, and give pertinent dates, including estimated date of
12. Describe proposed or completed operations. (Clearly state all perti- starting any proposed work). SEE RULE 1103. For Multiple Comp	nent details, and give pertinent dates, including estimated date of oletions: Attach wellbore diagram of proposed completion or
starting any proposed work). SEE RULE 1103. For Multiple Comp	pletions: Attach wellbore diagram of proposed completion or
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" of	onducted by Benterra Corporation to demonstrate the
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" coplugging and abandonment process using highly compressions.	onducted by Benterra Corporation to demonstrate the
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" of	onducted by Benterra Corporation to demonstrate the
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compression.	onducted by Benterra Corporation to demonstrate the
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" coplugging and abandonment process using highly compressions.	onducted by Benterra Corporation to demonstrate the
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compressed medium.  Tagged bottom @ 3665'	oletions: Attach wellbore diagram of proposed completion or conducted by Benterra Corporation to demonstrate the essed sodium bentonite nodules as the plugging  Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  17 cu ft Zonite 19 cu ft Zonite	oletions: Attach wellbore diagram of proposed completion or conducted by Benterra Corporation to demonstrate the essed sodium bentonite nodules as the plugging  Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compressed buttom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  SEE RULE 1103. For Multiple Compression in the Number of Section 12 of Section 2 of	Tagged Tagged Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  17 cu ft Zonite 19 cu ft Zonite 16 cu ft Zonite	oletions: Attach wellbore diagram of proposed completion or conducted by Benterra Corporation to demonstrate the essed sodium bentonite nodules as the plugging  Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compressed buttom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  SEE RULE 1103. For Multiple Compression in the Number of Section 12 of Section 2 of	Tagged Tagged Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  4 cu ft Zonite	Tagged Tagged Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.	Tagged Tagged Tagged Tagged Tagged Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  4 cu ft Zonite	Tagged Tagged Tagged Tagged Tagged Tagged Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compressed medium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  Thereby certify that the information above is true and complete to the began 10/8/01 and were completed 3/28	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compression.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best signature.	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compression.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best SIGNATURB & Liplay   Market   Market	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Compression.  This well is part of the New Mexico "P&A Pilot Project" complugging and abandonment process using highly compression.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best signature.	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" of plugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best SIGNATURE.  Type or print name J.K. Ripley  Type or print name J.K. Ripley  Type or State use)	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" of plugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best of the plug and the p	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" of plugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best of the plug o	Tagged
starting any proposed work). SEE RULE 1103. For Multiple Comprecompilation.  This well is part of the New Mexico "P&A Pilot Project" of plugging and abandonment process using highly compremedium.  Tagged bottom @ 3665'  Bottom Plug @ 3543' – 3665'  Bottom Plug @ 2901' – 3040'  T/Salt Plug @ 2901' – 3040'  T/Salt-Rustler Plug @ 1471' – 1580'  FW/Shoe Plug @ 410' – 530'  Top Plug @ 3' – 33'  Set Marker. Chevron to clean location.  Plugging operations began 10/8/01 and were completed 3/28  I hereby certify that the information above is true and complete to the best of the plug and the p	Tagged



## Final P&A **Schematic**

Seven Rivers Queen Waterflood, North #012 WELL NAME:

30-025-28925

API NUMBER COORDINATES:

1305' FSL & 2635' FEL Unit O

SEC/TWN/RNG: COUNTY/STATE: Lea, NM

DRILLED

4 - 22S - 36E 1984

OPERATOR:

Chevron

FIELD: DATE: South Eunice April 17, 2002

BY:

CRS/MCB

RKB = 13'

Formation Tops				
Rustler	1526'			
Salt	1610'			
Yates	3140'			
7 Rivers	3370'			
Queen	3725'			

Top Plug @ 3' - 33' 4 cu ft Zonite Wiper Plug @ 33'

> Legend Cement ZONITE

85/8" 24 - 28# @ 480' w/ 350 sx, circ

ZONITE	Plugs
--------	-------

3' - 33' Top Plug

FW/Shoe Plug 410' - 530'

T/Salt-Rustler

1471' - 1580' 2901' - 3040'

B/Salt Plug Bottom Plug

3543' - 3665'

Top of fill 3665' Packer @ 3689' FW/Shoe Plug @ 410' - 530' 16 cu ft Zonite Wiper Plug @ 530'

T/Salt - Rustler Plug @ 1471' - 1580'

15 cu ft Zonite Wiper Plug @ 1580'

Top of Salt = 1610'

B/Salt plug @ 2901' - 3040' 19 cu ft Zonite

Wiper Plug @ 3040'

Bottom Plug 3543' - 3665' 17 cu ft Zonite

Perfs: 3782 - 3860' overall

51/2" - 15.5# K55 LTC @ 3970" w/ 1100 sx, circ to surf

3926' PBD

3970' TD



# **Daily Operations Summary**

OPERATOR Chevron U.S.A. Production Company  LEASE & WELL NUMBER Seven Rivers Queen Waterflood, North #12			DATE					
			See Below  County & State  Lea, New Mexico					
				FIELD			FORMATION	
				South Eunice		Queen		
TD	PBD	RKB	PERFS					
3970'	3926'	13'	3782' – 3860'					
SURFACE	INTERMEDIATE	PRODUCTION	CIBP DEPTH					
85/8" @ 480'		5½" @ 3970'	None					
OPERATOR CHARGE CODE		BENTERRA CHARGE CODE						
UPWPBA1008ABN		NWNMR-00101-013						

This well is part of the New Mexico "P&A Pilot Project" conducted by Benterra Corporation to demonstrate the plugging and abandonment process using highly compressed sodium bentonite nodules as the plugging medium.

#### 10/8/01

MIRU Benterra Unit #4. SIP = STATIC. RU Key pump truck to displace hole, pump 20 bbl FW and press to 500 psi. Could not pump into perfs with 500 psi and no bleed down. Press to 1000 psi with same result. RD pump truck and Benterra. Moved Benterra back to tag btm. WIH with WL and tagged at 3665' = 24' above reported pkr setting depth and 117' above top perf. RD Benterra.

### 10/9/01

Discussed wellbore with Chevron's Nathan Mouser. Noted that we couldn't be certain that fresh water was present at btm plug depth and that FW hydration was preferred over produced water. Nathan thought the well had FW pkr fluid and this was probably what remained in the wellbore. Also, this waterflood never responded (low bottom hole pressure) and the fact that we couldn't pump in with 1000 psi, Nathan thought that a produced water plug was acceptable. Closed discussion with proposal that Benterra would go forward with plugging if NMOCD approved. Discussed with E.L. Gonzalez with NMOCD; he approved setting btm plug without cleaning out fill or displacing wellbore w/ fresh water. Plug to be placed from 3665' with minimum height of 100'. Will monitor per pilot protocol. E.L. noted that no cavity shots were required and csg would not be pulled, therefore, if problem developed in future, well could be easily re-entered.

#### 10/10/01

SIP = static. Removed WH. Poured 17 cu ft of ZONITE, wait and tagged at 3543'. Bottom plug set from 3543' - 3665' (122') w/ 17 cu ft ZONITE as of 2:35 PM 10/10/01. RD Benterra.

#### 10/25/01

MIRU Benterra Unit #4. SIP = static. Remove WH. WIH with SB and tag plug at 3543', OK. FL at 40'. Pushed 5½" wiper rubber to 3040'. Poured 10 cu ft ZONITE, wait and tag at 2969'. (Note: oil in wellbore). RD Benterra. Will road to Eunice to load ZONITE.

#### 10/26/01

MIRU Benterra Unit #4. SIP = static. Remove WH. Poured 9 cu ft ZONITE, wait and tag at 2901'. Fluid at surface – some oil. B/Salt plug set from 2901' – 3040' (139') with 19 cu ft ZONITE as of 10:00 AM 10/26/01. Pushed 5½" wiper rubber to 1580'. Poured 11 cu ft ZONITE, wait and tag at 1501'. Poured 4 cu ft ZONITE, wait and tag at 1471'. T/Salt – Rustler plug set from 1471' – 1580' (109') with 15 cu ft ZONITE as of 12:50 PM 10/26/01. Install WH and SWI. RD Benterra.

# Page 2 'Seven Rivers Queen Waterflood, North #12 11/26/01 MIRU Benterra Unit #4. SIP = static. Remove WH. Made trip with SB and tag plug at 1470', OK. Push 51/2" wiper rubber to 530'. Poured 8 cu ft ZONITE, wait and tag at 470'. Poured 8 cu ft ZONITE, wait and tag at 410'. Fresh water - 85/8" shoe plug set from 410' - 530' (120') with 16 cu ft ZONITE as of 1:45 PM 11/26/01. Push 51/2" wiper rubber to 33', poured 4 cu ft ZONITE and filled 51/2" csg to surface. Top plug in place as of 2:45 PM 11/26/01. RD Benterra. 12/10/01 Wellbore open to atmosphere - fluid at surface, no bubbling. Install WH and SWI to determine if there is any pressure buildup. 12/19/01 SIP = static. 1/9/02 SIP = static. 1/28/02 Add water to cover top of ZONITE plug, no bubbling. 2/20/02 Check location - no problems. 3/14/02 Check location - no problems. 3/18/02 Check location - water on top plug w/ no bubbling. Surface/Intermediate risers are open & static. 3/28/02 Key Energy Services dug out cellar & cut off wellhead & casings to 4' below GL. Poured 40 gals ZONITE into 85/8" x 51/2" annulus. Welded on cap with 1/2" brass valve and installed dry hole marker with well

identification. Dug out and cut-off guywire anchors @ 4' below GL. Back-filled all excavations. Turned

over to ChevronTexaco for location cleanup and NMOCD inspection. Final Report.