

11-17-80 CREW OFF.
 11-18-80 CO SD 3372-3735 PBD, CIRC CLEAN, POH.
 11-20-80 RIH W/OTIS NP PERMALATCH OSTSD W/TYPE N LANDING NIPPLE AND SN ON 2-7/8
 WS. SET PKR 2806. REMOVE BOP. TEST TO 500 W/5% KCL. SWAB 4 HRS.
 VERY SLIGHT GAS.
 11-21-80 SWAB 6 HRS NO FLUID, NO FE TO SN @ 2798. UNSEAT PKR, INSTALL BOP.
 11-22-80 LWR TBG & PKR TO 3395, SPOT 750 GALS 15% NEHCL ACID 3395-2895. RAISE
 PKR, INSTALL WELLHEAD. ACDZ PERFS 2910-3395 W/6000 GALS 50 QUALITY
 FOAMED 15% NEHCL ACID.
 11-23-80 3½ HRS - NO FLUID OR GAS. SI FOR BHP.
 11-24-80 CREW OFF.
 11-25-80 RAN 44 HRS. SI BHP 179 PSI @ 3150.
 11-26-80 UNABLE TO FRAC. ATTEMPT TODAY.
 11-27-80 FRAC PERFS 2910-3395 W/50000 GALS 70 QUALITY FOAM NITROGEN AND 5% KCL
 & 40000 LBS.
 11-28-80 CREW OFF. FLOWING
 11-29-80 WELL FLOWING. RAN GAUGE RING TO 2798 TOP PKR SET 2" TYPE SN TBG PLUG
 @ 2798.
 11-30-80 RAN TBG SEAL DIVIDER AND SN ON 2-3/8 TBG, CIRC W/TREATED 2% KCL WTR
 LATCH ONTO PKR @ 2798. PULL SN TBG PLUG ON WIRELINE.
 12-1-80 CREW OFF.
 12-2-80 TIED WELL INTO EL PASO GATH SYS. EL PASO TO REPAIR LEAK.
 12-3-80 OPEN 10:30 AM, 1" CHK, TP 100, 968 MCF/D.
 12-4-80 FLOWING - NO OIL. 2 BLW, 1" CHK, TP 85, 859 MCF/D.