

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-04901
6. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
8. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name W.A. RAMSAY(NCT-A)
8. Well No. 49
9. Pool name or Wildcat SOUTH EUNICE
10. Elevation(Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL _____ GAS _____
WELL WELL OTHER _____

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS

4. Well Location
Unit Letter **M** : **660'** Feet From Th **SOUTH** Line and **660'** Feet From The **WEST** Line
Section **34** Township **21S** Range **36E** NMPM **LEA** County

11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	OTHER: _____ <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO:
SET CIBP AT 3700' SPOT 700' CMT F/3700'-3000'.
PERF AT 1700', SET CICR AT 1500', SQZ W/50 SX. CMT LEAVE 35' ON TOP. PLUG COVERS RUSTLER & SALT.
PERF AT 500' PUMP 125 SX CMT AND CIRC BETWEEN 5 1/2" & 8 5/8" CSG. LEAVING 5 1/2" FULL.
10# P & A MUD WILL BE PLACED BETWEEN ALL CMT. PLUGS.
CUT OFF WELLHEAD AND INSTALL P & A MARKER.
CHANGE WELL STATUS TO P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P. R. Matthews TITLE **TECH. ASSISTANT** DATE: **5-8-92**

TYPE OR PRINT NAME **P.R. MATTHEWS** TELEPHONE NO (915)687-7812

APPROVED BY JERRY DIXON TITLE **SUPERVISOR** DATE **MAY 11 '92**

CONDITIONS OF APPROVAL, IF ANY: