

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                |                                                                                 |
|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|
| 1. CIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                               | 7. Unit Agreement Name<br>NORTHEAST DRINKARD UNIT                               |
| 2. Name of Operator<br>SHELL WESTERN E&P INC.                                                                                                  | 8. Farm or Lease Name<br>NORTHEAST DRINKARD UNIT                                |
| 3. Address of Operator<br>P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)                                                                          | 9. Well No.<br>803                                                              |
| 4. Location of Well<br>UNIT LETTER C 660 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 22 TOWNSHIP 21S RANGE 37E N.M.P.M. | 10. Field and Pool, or Wildcat<br>NORTH EUNICE BLINEBRY-TUBB-DRINKARD OIL & GAS |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3416' GR                                                                                      | 12. County<br>LEA                                                               |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

| NOTICE OF INTENTION TO:                        |                                                           | SUBSEQUENT REPORT OF:                                |                                               |
|------------------------------------------------|-----------------------------------------------------------|------------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/>                 | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                     | COMMENCE DRILLING OFHS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER SQZ, OAP & ACDZ <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. Set CIBP's @ 6540' & 6480'.
3. Set pkr @ 6300'.
4. Sqz Drinkard perms 6387' - 6468' w/25 sx Cls "C" cmt + .3% D-60 followed by 25 sx Cls "C" cmt + 2% CaCl<sub>2</sub>. WOC 24 hrs.
5. POH w/pkr.
6. DO cmt to CIBP @ 6480'. Pres tst sqz to 500#.
7. DO CIBP's & CO to TD.
8. Perf Blinebry/Drinkard 5708' - 6469' (1 JSPF).
9. Acdz perms 5708' - 6628' w/11,130 gals 15% HCl-NEA + 1500# rock salt using RBP & pkr.
10. POH w/RBP & pkr.
11. Install prod equip & return well to prod.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Marcus Winkler A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE 4-25-88  
Orig. Signed by Paul Kautz Geologist  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: