

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
**E-7838**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>Dan C. Berry</b>	8. Farm or Lease Name <b>Sinclair State</b>
3. Address of Operator <b>c/o Oil Reports &amp; Gas Services, Inc., Box 763, Hobbs, N. M. 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>M</b> <b>3300</b> FEET FROM THE <b>South</b> LINE AND <b>330</b> FEET FROM THE <b>West</b> LINE, SECTION <b>1</b> TOWNSHIP <b>21 S</b> RANGE <b>33 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Lynch Yates-Seven River</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3802</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug for abandonment as follows:

100' plug above perforations 3762-84.  
To cut and pull 4 1/2" casing with 100' plug across  
stub; if recovered below base of Salt 100' plug at  
base of Salt and 100' plug at top of Salt  
100' plug across 13 3/8" casing shoe @ 250'  
10 sacks at surface with regulation marker.  
Mud between all plugs.  
Location to be cleared and levelled.

24 hr notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donna Holmes TITLE Agent DATE 10/27/72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE OCT 30 1972  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 3 - 1972

OIL CONSERVATION COMM.  
HOUSTON, N. M.