

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25323
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-3145
7. Lease Name or Unit Agreement Name	
Wilson State	
8. Well No.	1-Y
9. Pool name or Wildcat	Wilson (Strawn)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3646' GR	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator	Mitchell Energy Corporation
3. Address of Operator	Box 4000 The Woodlands, Tx 77387-4000
4. Well Location	Unit Letter C : 660 Feet From The North Line and 1480 Feet From The West Line
Section 19	Township 21S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-4-94 Set 5 1/2 CIBP at 11,100' Cap w/35' Cmt. Cut 5 1/2 csg. at 9000'  
6-7-94 Ran Tbg to 9050' Spotted 50 sxs cmt. Try to pull tbg. Tbg.  
stuck 5700'. WOC Tested stub plug to 1000#  
6-8-94 Cut 23/8 tbg. at 5700' Spotted 60 sxs Cmt Pull out of hole  
WOC Tag plug at 5584' Pull out of w/tbg to 3600'. Spotted  
Spotted 60 sxs cmt. Pull out of hole w/tbg to 425'. Spotted  
15 sxs cmt at surface

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry Dickman TITLE Supervisor DATE 6/8/94  
TYPE OR PRINT NAME Larry Dickman TELEPHONE NO. 915-362-4324

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE