

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instruction on
reverse side)

SECRET ORDER NO. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	Jan 17 10 51 AM	7. UNIT AGREEMENT NAME <i>South Eunice Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>		8. FARM OR LEASE NAME <i>South Eunice Unit</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>		9. WELL NO. <i>36</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>660' FNL & 1980' FEL - Unit Letter B</i>		10. FIELD AND POOL, OR WILDCAT <i>Eunice 7 River Queen S</i>
14. PERMIT NO. <i>30-025-09077</i>	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>28-225-36 E</i>
		12. COUNTY OR PARISH <i>Lea</i>
		13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other) <i>CO, Open Add'l Pay & Acidize</i>	☒		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRR. If necessary, kill well. POOH w/ rods & pump. Install BOP.
2. Tag for fill w/ 2 3/8" Hg & tally out of hole.
3. If fill above 3800', G1H w/ 4 3/4" bit, bailed & 2 7/8" workstring. Clean out to 3820' & POOH.
4. G1H w/ 4 3/4" bit, 5 1/2" csg scraper & 2 7/8" Hg. Run bit to 3800' & POOH.
5. G1H w/ 4" centralized csg gun. Perf 3720' - 3731' w/ 4 SSPF for a total of 20 shots. POOH.
6. G1H w/ 5 1/2" treating pke & set at 3550'.
7. Acidize from 3652' - 3783' w/ 150 bbls 15% HCL-NE-FE acid inhibited for 24 hrs at 100°F. Pump 600 # graded rock salt mixed in 5 bbls gelled 9" brine in 3 equal stages. Flush w/ 80 bbls 9" brine.
8. Swab well. Release pke at 3550' & POOH.
9. Land SN at 3766'. Run rods & pump. Place well on production. For further information contact Jay Vashler at 397-5866.

18. I hereby certify that the foregoing is true and correct

SIGNED *W. J. Finney* TITLE *Administrative Supervisor* DATE *January 12, 1989*

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

JAN 26 1989

EB

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Carlsbad (6) ARCO (2) AMOCO (2) Chevron (1)

RECEIVED

JAN 30 1993

OCD
HOBBS OFFICE