

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT TO DEEPEN OR PLUG BACK" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
N.M. 03372-12
16-032573 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

MAR 29 11 56 AM '66

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

Box 460, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1650' FSL and 990' FEL of Section 15,
T-22S, R-37E, Lea County, New Mexico, NMPM.

7. UNIT AGREEMENT NAME

NMPU

8. FARM OR LEASE NAME

Elliott B-15

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

NMPU Field
Drinkard

11. SEC., T., R., S., OR BLK. AND
SURVEY OR AREA

S-15, T-22S, R-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3372 DF

12. COUNTY OR PARISH

Lea

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Plugback and Recomplete

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

To restore a shut-in well to production, it is proposed to plugback and recomplete Elliott B-15 No. 2 in the Drinkard formation using the following procedures:

1. Set Ret. @ 7350 and spot 20 sks Class "C" cement.
2. Run Gamma Ray-Neutron-Collar Log from 6,600' to 5,000'.
3. Perforate Drinkard with one shot per foot @ approximately 6397, 6412, 6422, 6443, 6459, 6469, 6480 and 6498' (Exact depth to be picked from new log).
4. Treat with 4000 gals acid (1/2% HC2), using ball sealers.
5. Test well and place on production.

Your approval is respectfully requested.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Staff Supervisor

DATE 3-8-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

USGS-5, At1 Ros-2, Pan Am Hobbs-2, Calif Mid-2 File

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

MAK SD 11 28 AM '68
U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229