

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State Farm

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- _____

2. Name of Operator
Gulf Oil Corporation

3. Address of Operator
P. O. Box 670, Hobbs, NM 88240

4. Location of Well
UNIT LETTER N 810 FEET FROM THE South LINE AND 1930 FEET FROM
THE West LINE, SECTION 6 TOWNSHIP 22S RANGE 37E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
H. T. Mattern (NCT-D)

9. Well No.
13

10. Field and Pool, or Wildcat
Blinebry

15. Elevation (Show whether DF, RT, GR, etc.)
3457' GL

12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <u>DHC Blinebry, Tubb, Drinkard (R-7238)</u> <input checked="" type="checkbox"/>		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment. Drill out CIBP @ 6100' and push below bottom Drinkard perf as far as possible. Acz Tubb and Drinkard with 5000 gals 15% NEFE HCL, (108) RCNB's, rock salt and benzoic acid. Close in well 1 hr; open well and swab. GIH with 2-3/8" tubing. RIH with rods and pump. Hang well on. Kick off.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDPitre TITLE Area Engineer DATE 4-28-83

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE MAY 2 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
APR 29 1983
HOBBY OFFICE