(I	eb. 19	951)	
Ì			
	X		

Form 9-831 a

1 0 ± 020 . St 0 0 0 =

Approved by (SUBMIT IN TRIPLICATE) E. W. Standley 8/8/62. UNITED STATES

Land Office	
Lease No.	NH 04747
Unit	

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE P	LANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATE	ł	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR	ACIDIZE	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR A	ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON	WELL	
(INDICA	TE ABOVE BY CHECK MARK I	NATURE OF REPORT, NOTICE, OR OTHER DATA)
		June 21 196
Continental Federal		, 17-
Well No. 1 is locat	ted 1980 ft. from	$\begin{cases} \mathbf{X} \\ \mathbf{S} \end{cases} \text{ line and } \begin{array}{c} 660 \\ \text{ft. from } \\ \mathbf{W} \\ \end{array} $ line of sec. 1
MILI/I CH/I Con 7	21. 9	22 E NMPM
(½ Sec. and Sec. No.)	(Twp.) (32 E NMPM Range) (Meridian)
	_	
Wildcat (Field)	(County or	Subdivision) (State or Territory)
State names of and expected depths to	o objective sands; show size ing points, and all ot	es, weights, and lengths of proposed casings; indicate mudding jobs, ceme ther important proposed work)
	المحمطة المحمدة	a material control of the control of
Subject well was pl	magain and anamid	oned 5/25/62 as follows:
Spotted 35 sacks ce mud. Shot off 4 1/ shot point 3150-325	ment on top bridge casing at 3250, 12 sacks 1256 at surface.	oned 5/25/62 as follows: dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared
Spotted 35 sacks ce mud. Shot off 4 1/ shot point 3150-325 at 312 and 10 sacks	ment on top bridge casing at 3250, 12 sacks 1256 at surface.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe
Spotted 35 sacks ce mud. Shot off 4 1/ shot point 3150-325 at 312 and 10 sacks	ment on top bridge casing at 3250, 12 sacks 1256 at surface.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe
Spotted 35 sacks ce mud. Shot off 4 1/ shot point 3150-325 at 312 and 10 sacks	ment on top bridge casing at 3250, 12 sacks 1256 at surface.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared
Spotted 35 sacks ce mud. Shot off 4 1/ shot point 3150-325 at 312 and 10 sacks	ment on top bridge casing at 3250, 12 sacks 1256 at surface.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe
Spotted 35 sacks ce mud. Shot off 4 1/ shot point 3150-325 at 312 and 10 sacks	ment on top bridge casing at 3250, 12 sacks 1256 at surface.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared
Spotted 35 sacks ce mud. Shot off 4 1/shot point 3150-325 at 312 and 10 sacks and levelled locati	ment on top bridge casing at 3250, 12 sacks 1256 at surface. Estimate	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared
Spotted 35 sacks ce mud. Shot off 4 1/shot point 3150-325 at 312 and 10 sacks and levelled locati	ment on top bridge casing at 3250, 12 sacks 1256 at surface. Estate consequently and the surface approval in the surface approximate appro	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared
Spotted 35 sacks ce mud. Shot off 4 1/shot point 3150-325 at 312 and 10 sacks and levelled locati	ment on top bridge casing at 3250, 12 sacks 1256 at surface. Estimate constitution corp.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared COPY writing by the Geological Survey before operations may be commenced.
Spotted 35 sacks ce mud. Shot off 4 1/shot point 3150-325 at 312 and 10 sacks and levelled locati I understand that this plan of work Company Cabeen Expl. Address c/o Cil Rep.	ment on top bridge casing at 3250, 12 sacks 1256 at surface. Estimate constitution corp.	dge plug at 5038 and loaded hole with 00 and pulled. Spotted 12 sacks across 0-1380, 20 sacks across 8 5/8" shoe rected regulation marker and cleared COPY writing by the Geological Survey before operations may be commenced.