

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Conservation  
1625 N. French Dr.  
Hobbs, NM 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Primal Energy Corporation

3. Address and Telephone No.

211 Highland Cross #227, Houston, TX 77073 (281)821-5600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit G, 1980' FNL & 1980' FEL, Sec. 11, T24S, R32E

5. Lease Designation and Serial No.

NM02889

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Wimberly #1

9. API Well No.

30-025-08140

10. Field and Pool, or Exploratory Area

Double X Delaware

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. POOH with all production equipment.
2. Set cement plug with 30 sxs. from 4650' to 5050'. Set second plug w/25 sxs. in same spot. Tag 2nd plug at 4533'.
3. Fill hole with mud. Cut and pull 4 1/2" casing at 1005'. Set 25 sx. plug at 2500'. Set plug from 1050 to 931' after four attempts. Tag plug. Spot 50 sx plug from 420' to 300'. Tag at 340'. Set 25 sx. at 340. Set 20sx surface plug at 50'.
4. Erect dry hole marker. Clean and restore location.

Plugging supervised by Steve Caffay.

P&A effective 5/15/2000

Approved as to plugging of the well bore  
Liability under bond is retained until  
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct.

Signed

Title Manager, Operations & Engineering

Date June 12, 2000

(This space for Federal or State office use)

(ORIG. SGD.) ALEXIS C. SWOBODA

PETROLEUM ENGINEER

Approved by Title

Date JUN 21 2000

Conditions of Approval, if any:

Title 18 U.S.C. Section 101, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

See Instructions On Reverse Side

GW

