

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
NM 2 A

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Pacific Oil Company, Inc.	8. Farm or Lease Name State "A" A/c-1
3. Address of Operator P. O. Box 1069, Hobbs, New Mexico 88240	9. Well No. 54
4. Location of Well UNIT LETTER I , 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 23-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3333 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and Rig up. Pull rods, pump and tubing.
2. Set CIBP at 3490'.
3. Perf 3395 - 3464' (9 holes) with 3/8" jet charge.
4. Set packer at 3375' and acidize with 2500 gal. 15% N.E.
5. Pull packer. Run tubing and swab.
6. Run rods and pump to test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED **Sheldon Ward**

TITLE **Area Superintendent**

DATE **May 8, 1970**

APPROVED BY 

TITLE **SUPERVISOR**

DATE **MAY 11 1970**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 8 1970

OIL CONSERVATION COMM.
HONOLULU, H. I.