December 15, 1950

Oil Well Remedial Service Box 511 Odessa, Texas

Gentlemen:

We are returning herewith forms 3-104 and 6-110, or which you are to correct the unit designation. On both of these forms you have indicated that the well is located in Unit P, whereas the foot location is shown as 2310 feet from the North line and 330 feet from the East line of Section 13-24-36. This description would place the well in Unit H.

As soon as you have made this correction, please return for an assignment of allowable.

Yours very truly,

OIL CONSERVATION COMMISSION

A. L. Porter, Jr. Proration Manager

ALP/mv

cc: Roy Yarbrough