

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
reverse side)7E
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0559129

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TEXACO Inc.	8. FARM OR LEASE NAME C.E. Penny Fed. NCT-4
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico 88240	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well is located 1980' from the North line and 1650' from the West line of Section 19, T-25-S, R-38-E, Unit Letter F.	10. FIELD AND POOL, OR WILDCAT Langlie Mattix
11. PERMIT NO. Regular	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T-25-S, R-38-E
12. ELEVATIONS (Show whether DF, RT, GR, etc.) 3081' DF	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐(Other) ☐Convert to Injection (SWD) ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. SERIAL PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The following work on subject well has been completed:

1. Tag bottom w/tubing and clean to TD (3415') with sand pump.
2. Ran 2-7/8" plastic coated tubing w/Guiberson tension shorty packer and set at 3230'.
3. Install wellhead, connect to SWD line and began injection.
4. Cleaned location.

Work completed 11-12-70

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Assistant District
Superintendent

DATE March 31, 1971

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

APR 2 1971

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO