N.M Cor

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR ECEIVEUREAU OF LAND MANAGEMENT

Hobbs. NM 88241 RECEIVED

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

Date 09/11/97

Date SEP 24 1997

Do not use this ferm to proposals to dr Use "APPLICATION FO	AND REPORTS ON WELLS 1997 SEP 13 P 12: ill or to deepen or reentry to a different reservoir DR PERMIT-" for such properties U OF LAND M	· GMT.	
ROSWELL OF FRUIDMIT		0r. If Unit or CA, Agreement Designation	
1. Type of Well Oil Well Well Other WIW 2. Name of Operator		8. Well Name and No. Eva E. Blinebry #14	
PLAINS PETROLEUM OPERATING COMPANY 3. Address and Telephone No.		9. API Well No. 30-025-21695	
415 W. WALL, SUITE 1000 MIDLAND, TX 79701 915/683-4434 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area Langlie Mattix 7 Rvrs Queen GB	
2660' FNL & 20' FEL , Sec. 35 (I), T23S, R37E		11. County or Parish, State LEA, NM	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O	<u> </u>	
TYPE OF SUBMISSION	TYPE OF ACTION	TYPE OF ACTION	
Notice of Intent	Abandonment Recompletion	Change of Plans New Construction	
Final Abandonment Notice	☐ Plugging Back ☐ Casing Repair ☐ Altering Casing ☐ Other	Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Describe Proposed or Completed Operations (Clearly s directionally drilled, give subsurface locations and measurements)	tate all pertinet details, and give pertinent dates, including estimated date sured and true vertical depths for all markders and zones pertinent to this	of starting any proposed work. If well is	
Kill well with 10 ppg Brine, NU BOP			
(1) Release AD-1 pkr, POOH w/2-3/8" IP	C tbg , lay dwn IPC tbg & pkr.		
(2) PU, tally & GIH w/2-3/8" tbg workstring & psi.	& 4-1/2" cement retainer, set cement retainer @ 3350'.	Pressure test tbg & csg to 500	
(3) Mix, pump & squeeze perforations belo csg w/10 ppg gel-chem mud. Pull tbg out o	w CR w/75 sx Premium Plus cement. Pull out of retain f hole up to approximately 1600'.	er, circulate and displace tbg,	
(4) Mix, pump & spot 10 sx Premium Plus (13.2 cu ft) or 145' vertical cement plug inside the 4-1/2"	csg.	
(5) Pull tbg out of the hole up to 355'. Mix, a 4-1/2" csg) & opposite the 7-5/8" surface cs	pump & spot 10 sx Premium Plus cement plug 50'+ abo g shoe.	ove & 50'+ below (inside the	
(7) Pull tbg up to 20' & spot 20' Premium Pli marker in the surface cement plug.	us plug back to surface, cut off wellheads 3'-5' below G	SL & embedded w/dry hole	
14. I hereby certify that the foregoing is true and correct			

SEE ATTACHED FOR

(This space for Federal or State office use)

Title 18 U.S.C. Section 100 S makes it admirite for the son knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

District Manager