

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name E. C. Winters
2. Name of Operator Meridian Oil Inc.	8. Well No. 1
3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810	9. Pool name or Wildcat Jalmat Tansil Yates 7-Rvrs
4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>18</u> Township <u>25S</u> Range <u>37E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3113' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify OCD prior to commencing plugging operations.

RIH w/casing scraper to +/- 2750', set cmt retainer @ +/-2725'. Squeeze open hole under retainer with 100 sx Cl. C cmt. Spot cmt plug @ 2370'-2725' (65 sx). Circ hole with 9 ppg gelled brine.

Set cement plug @ 1480' - 1600' (25 sx). Perforate 4 squeeze holes @ 355'. Squeeze 7" x 10-3/4" annulus by pumping 200 sx cmt (40% excess) from surface. Leave cmt in 7" casing to surface (do not displace). Use Cl. C cmt.

Cut off casing 3' below ground level and install P&A marker. Clear and restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Connie L. Malik TITLE Reg. Compliance Rep. DATE 3/31/92

TYPE OR PRINT NAME Connie L. Malik TELEPHONE NO. 915-688-6898

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 02

CONDITIONS OF APPROVAL, IF ANY:  
THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE OIL

**MERIDIAN OIL**  
WINTERS NO. 1  
JALMAT FIELD  
LEA COUNTY, NEW MEXICO

KLM 11/18/91

PROPOSED CONDITION AFTER P&A

