

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)TE*
re-Form approved.
Budget Bureau No. 42-B1424.
5. LEASE DESIGNATION AND SERIAL NO.

LC 032579(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Fed. Lease

8. FARM OR LEASE NAME

Carlsen R 26

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Justin Tubb Brk.-Blinebry

11. SEC. T. R. M., OR BLM. AND
SURVEY OR AREA

26-258-37E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Dual AFR 11 05 AM '67	2. NAME OF OPERATOR Westates Petroleum Company	3. ADDRESS OF OPERATOR Box 55, Jal, New Mexico	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' from S. & 330' from E. Sec. 26, 25S., 37E. NE 1/4 SE 1/4 Sec. 26, Lea County, New Mexico	14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3054' Ground level
--	---	---	--	----------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7" 23# casing at 6249' Dual packer 55400'. Producing Blinebry 5094'-5098'; 5131'-5138'. Present production 28 BOPD.

We propose to acidize Blinebry w/10,000 gal. super X 28% acid in 2 stages w/salt plug between stages, over flush each stage w/5000 gal. 3% acid. Set production packer at approximately 5575' and FSA at 5370'. Seal and test Drinkard zone 5850'-5930'. Assuming Drinkard zone is predominantly water productive, plug back with cast iron plug to approximately 5825'. Acidize Tubb zone 5784' to 5804' w/7500 gal. super X 28% acid using salt plug between stages. Each stage to be over flushed w/5000 gal. 3% acid.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Prod. Supt.

DATE

3-18-67

(This space for Federal or State office use)

APPROVED BY

TITLE

W. Z. Stuck

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-845229

847-851