District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com	Incident # (assigned by OCD)
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	

Location of Release Source

Latitude: 32.11126 Longitude: -103.55611

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Rojo 14-17 Tank battery	Site Type: Tank Battery/Production Facility	
Date Release Discovered: 3/3/2021	API# (if applicable) Nearest well: Rojo 7811 22 Fed Com #014Y	
	API #30-025-45446	

Unit Letter	Section	Township	Range	County
Р	22	25S	33E	Lea

Surface Owner: State	☐ Federal ☐ Tribal	Private (Name: CAM Ltd,,	P.O. Box 3157,	, San Angelo, TX 76902)
------------------------	--------------------	--------------------------	----------------	-------------------------

Nature and Volume of Release

Material	(s) Released (Select all that apply and attach calculations or specific	justification for the volumes provided below)	
Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)	
☐ Produced Water	Volume Released (bbls) 277 BBL	Volume Recovered (bbls) 240 BBL	
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	⊠ Yes □ No	
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
☐ Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)	
Cause of Release			
Piping Failure and Overflow Secondary Containment.			
A fire tube was pulled from the heater treater for repairs. A check valve failure had allowed produced water to flow back into the dismantled treater and spill inside the unlined containment area. (See attached spill calculation spreadsheet.)			

Received by OCD: 5/7/2021 11:55:34 AM Form C-141 State of New Mexico

Oil Conservation Division

Page	2
1 ago	~

Page 2 of 4 Incident ID District RP Facility ID Application ID

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☐ No	If YES, for what reason(s) does the responsible party consider this a major release? The spill volume was greater than 25 BBL, which the NMOCD Rules define as a major release.
1	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? rided by an email sent 3/3/2021 to NMOCD.
	Initial Response
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
Released materials ha	ease has been stopped. Is been secured to protect human health and the environment. It been contained via the use of berms or dikes, absorbent pads, or other containment devices. It is been removed and managed appropriately. If above have not been undertaken, explain why:
has begun, please attach	AC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environment failed to adequately investigation	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have at and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
Printed Name: Bob Hall	Title: Environmental Manager
Signature: Be	26 Jall Date: 3/9/2021
email: bhall@btaoil.co	om Telephone: 432-682-3753
OCD Only	
Received by:	Date:

Location Rojo 14-17 Tank Battery

API#

Spill Date 3/3/2021

Spill Dimensions

ENTER - Length of Spill **ENTER** - Width of Spill **ENTER** - Saturation Depth of Spill

ENTER - Porosity Factor 0.03 decimal

Oil Cut - Well Test / Vessel Throughput or Contents

Oil 0.01 Water 99.99 Calculated Oil Cut 0.0001

Volume Recovered in Truck / Containment

ENTER - Recovered Oil **BBL ENTER** - Recovered Water

Calculated Values

Release of Oil in Soil - Unrecovered 0 **BBL** 37 **BBL** Release of Water in Soil - Unrecovered 37 **BBL Unrecovered Total Release**

Calculated Values

Total Release of Oil 0 **BBL** 277 BBL Total Release of Water **Total Release** 277

Types of Soil	Porosity Factor
Gravel	0.25
Sand	0.20
Clay/silt/sand Mix	0.15
Clay	0.05
Caliche	0.03
Unknown	0.25

(Length X Width X Depth X 1 ft/12 in) X Porosity 5.615 ft³ / BBL

Oil Cut X (or Water Cut)

83.2 **feet**

83.2 **feet**

calculated

calculated

BBL

12 inches

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 27346

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
BTA OIL PRODUCERS, LLC	104 S Pecos	Midland, TX79701	260297	27346	C-141

OCD	Condition
Reviewer	
rmarcus	The submitted C-141 is accepted with the following condition(s): The lateral and longitudinal information does not match the ULSTR regarding the release location. Please correct the conflicting
	information and report back to OCD. The lat./long. is revealing the ULSTR as 0-22-25S-33E. Please revise and submit either corrected Latitude/Longitude or ULSTR.