

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2203942460
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Chevron USA	OGRID: 4323
Contact Name: Amy Barnhill	Contact Telephone: 432-687-7108
Contact email: ABarnhill@chevron.com	Incident # (assigned by OCD)
Contact mailing address: 6301 Deauville Blvd Midland, Tx 79706	

Location of Release Source

Latitude 32.13851083 _____ Longitude -103.66322782 _____
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Cotton Draw TB	Site Type: Oil
Date Release Discovered: 2-5-22	API# (if applicable)

Unit Letter	Section	Township	Range	County
M	10	25S	32E	Lea

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 86.87	Volume Recovered (bbls) 82
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 130.32	Volume Recovered (bbls) 123
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Internal corrosion on piping

<p>Was this a major release as defined by 19.15.29.7(A) NMAC?</p> <p><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No</p>	<p>If YES, for what reason(s) does the responsible party consider this a major release?</p>
<p>If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?</p> <p>Amy Barnhill e-mailed Mike Bratcher on 2-5-22 at 6:30pm</p>	

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Amy Barnhill Title: Water Specialist

Signature: Amy White Date: 2-8-22

email: ABarnhill@chevron.com Telephone: 432-687-7108

OCD Only

Received by: Ramona Marcus Date: 2/14/2022

Incident ID	nAPP2203942460
District RP	
Facility ID	
Application ID	

Spill Calculations:

These are approximate calculations are for fluid in soil. The standing fluid picked up was ~205 bbls.

Area 1

Shape: Circle

Secondary Containment?: No

Standing Liquid Dimensions: 3 ft x 48

Total Volume: 5.791 bbl

Water Cut: 60%

Oil Volume: 2.316 bbl

Penetration Depth: 48 in

Fluid to Soil Volume: .755 bbl

Water Volume: 3.475 bbl

Area 2

Shape: Rectangle

Secondary Containment?: No

Standing Liquid Dimensions: 22 ft x 3 ft x 5 in

Total Volume: 5.633 bbl

Water Cut: 60%

Oil Volume: 2.253 bbl

Penetration Depth: 5 in

Volume to Soil Volume: .735 bbl

Water Volume: 3.38 bbl

Area 3

Shape: Rectangle

Secondary Containment?: No

Standing Liquid Dimensions: 20 ft x 3 ft x .75 in

Total Volume: .768 bbl

Water Cut: 60%

Oil Volume: .307 bbl

Penetration Depth: .75 in

Fluid to Soil Volume: .100 bbl

Water Volume: 0.461 bbl

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 79615

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 79615
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	The submitted C-141 is accepted with the following condition(s): The lateral and longitudinal information does not match the ULSTR regarding the release location. Please correct the conflicting information and report back to OCD. The latitude and longitude information on the C-141 resulted in the following ULSTR: N-10-25S-32E.	2/14/2022