District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2204056995
District RP	
Facility ID	fAPP2201743006
Application ID	

Release Notification

Responsible Party

Responsible Party: BTA Oil Producers, LLC	OGRID: 260297
Contact Name: Bob Hall	Contact Telephone: 432-682-3753
Contact email: bhall@btaoil.com	Incident # (assigned by OCD) nAPP2204056995
Contact mailing address: 104 S. Pecos St., Midland, TX 79701	

Location of Release Source

Latitude: 32.32146 Longitude: -104.07383

(NAD 83 in decimal degrees to 5 decimal places)

			(1,112 00 111)	acciminate are	grees to a decimal places,	
Site Name: F	Pecos Irrig	ation #1-10 Ta	nk Battery		Site Type: Tank Battery	/
Date Release Discovered: 2/8/2022		API# (if applicable) Nearest well:				
TT. 'A T. A	G. A.	T 1	D		Carrie	1
Unit Letter	Section	Township	Range		County	
G	10	23S	28E	Eddy		
Surface Owne	Surface Owner: State Federal Tribal Private (Name: Rustler Hills II, PO Box 72, Orla, TX 79770) Nature and Volume of Release					

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

⊠ Crude Oil	Volume Released (bbls) 26 BBL	Volume Recovered (bbls) 0 BBL		
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)		
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No		
Condensate	Volume Released (bbls)	Volume Recovered (bbls)		
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)		
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)		
Cause of Release				
Piping Failure.				
Load Line detached at coupling for oil tank allowing the tank to empty onto the tank battery pad. Volume was determined from tank gauge prior to the load line detachment.				
(Spill calculation spreadsheet attached.)				

Page 2

State of New Mexico
Oil Conservation Division

	1 1.80 2 0
Incident ID	nAPP2204056995
District RP	
Facility ID	fAPP2201743006
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by 19.15.29.7(A) NMAC?	The release was larger than 25 BBI fluid
19.13.29.7(A) NVIAC:	The release was larger than 25 BBL fluid.
⊠ Yes □ No	
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
_	ent on NMOCD Permitting Portal that was assigned Incident ID # nAPP2204056995 on
2/9/2022.	
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.
	s been secured to protect human health and the environment.
	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
<u></u>	ecoverable materials have been removed and managed appropriately.
<u> </u>	d above have not been undertaken, explain why:
II all the actions accertoes	2 above have <u>not</u> been and taken, explain why.
	AC the responsible party may commence remediation immediately after discovery of a release. If remediation
	a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred at area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
I hereby certify that the info	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and
regulations all operators are	required to report and/or file certain release notifications and perform corrective actions for releases which may endanger
	ncnt. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have ate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In
addition, OCD acceptance of	f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
and/or regulations.	
Printed Name: Bob Hal	Title: Environmental Manager
Signature:	Date: 2/21/2022
email: bhall@btaoil.c	om Telephone: 432-682-3753
OCD Only	
Received by: Ramona	Marcus Date: 02/21/2022

NAPP2204056995

68 feet

68 feet

2.5 inches

Location Pecos Irrigation Load Line

API#

Spill Date 2/8/2022

Spill Dimensions

ENTER - Length of Spill
ENTER - Width of Spill
ENTER - Saturation Depth of Spill

ENTER - Porosity Factor 0.15 decimal

Oil Cut - Well Test / Vessel Throughput or Contents

 Oil
 99.999

 Water
 0.001

 Calculated Oil Cut
 0.99999

Volume Recovered in Truck / Containment

ENTER - Recovered Oil 0 BBL
ENTER - Recovered Water 0 BBL

Calculated Values

Release of Oil in Soil - Unrecovered 26 BBL
Release of Water in Soil - Unrecovered 0 BBL
Unrecovered Total Release 26 BBL

Calculated Values

Total Release of Oil
Total Release of Water
Total Release

calculated

calculated

26 **BBL** 0 **BBL** 26 **BBL**

Types of Soil	Porosity Factor
Gravel	0.25
Sand	0.20
Clay/silt/sand Mix	0.15
Clay	0.05
Caliche	0.03
Unknown	0.25

(Length X Width X Depth X 1 ft/12 in) X Porosity 5.615 ft³ / BBL

X Oil Cut (or Water Cut)

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 83020

CONDITIONS

Operator:	OGRID:
BTA OIL PRODUCERS, LLC	260297
104 S Pecos	Action Number:
Midland, TX 79701	83020
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
rmarcus	None	2/21/2022