District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

## **Release Notification**

### **Responsible Party**

			resp		<i>y</i>		
Responsible	Party: <b>Ente</b>	rprise Field Ser	vices, LLC	OGRID: 2	41602		
Contact Nam	ne: <b>Thomas</b>	Long		Contact Te	elephone: 505-5	99-2286	
Contact ema				(assigned by OCD).	nAPP2113437743		
Contact mail <b>87401</b>	ing address:	614 Reilly Ave,	Farmington, NN	Л			
			<b>Location</b> 6	of Release So	ource		
Latitude <b>36.3</b>	809334		Longitude	-107.396711	(NAI	D 83 in decimal degrees to 5 decimal places)	
Site Name Li	ndrith Con	npressor Statio	n	Site Type	Natural Gas C	ompressor Station	
Date Release Discovered: 5/14/2021		Serial Num	Serial Number (if applicable): N/A				
Unit Letter	Section	Township	Range	Coun	ity		
I	18	24N	5W	Rio Ar	riba		
Surface Owne			_ ,	Volume of I	Release	)	
Material(s) Released (Select all that apply and attach calculations or specific  Crude Oil Volume Released (bbls)			Volume Reco				
Produced Water Volume Released (bbls)				Volume Recovered (bbls)			
Is the concentration of dissolved chloride produced water >10,000 mg/l?			loride in the	☐ Yes ☐ No			
☐ Condensate Volume Released (bbls): <b>80 BLS</b>				Volume Reco	vered (bbls): <b>80 BBLs</b>		
Natural G	as	Volume Release	d (Mcf):		Volume Reco	vered (Mcf):	
Other (de	scribe)	Volume/Weight	Released (provide	units):	Volume/Weight Recovered (provide units)		

Cause of Release: On May 14, 2021, at approximately 9:45 a.m., Enterprise had a release of condensate from an above ground storage tank at Lindrith Compressor Station. Approximately 80 barrels of condensate were released into a lined secondary containment. No liquids were observed outside of the secondary containment. No residences were affected. No emergency services responded. The tank was drained and removed from service in the fall of 2021 and subsequent weather events caused a buildup of snow and ice on the containment liner not allowing it to be inspected. The liner was inspected by Enterprise Field Services, LLC and Jicarilla Apache Environmental Protection Office representatives on May 3, 2022 and found no tears or punctures.

Received by OCD: 5/23/2022 12:19:06 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

	-	use	-	•
Incident ID				
District RP				
Facility ID				
Application ID				

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the fo	following items must be included in the closure report.
A scaled site and sampling diagram as described in	19.15.29.11 NMAC
Note that Photographs of the remediated site prior to backfill must be notified 2 days prior to liner inspection)	or photos of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: approp	oriate ODC District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or may endanger public health or the environment. The accesshould their operations have failed to adequately investigated human health or the environment. In addition, OCD accessompliance with any other federal, state, or local laws and restore, reclaim, and re-vegetate the impacted surface areas	nd complete to the best of my knowledge and understand that pursuant to OCD rules file certain release notifications and perform corrective actions for releases which eptance of a C-141 report by the OCD does not relieve the operator of liability ate and remediate contamination that pose a threat to groundwater, surface water, ptance of a C-141 report does not relieve the operator of responsibility for d/or regulations. The responsible party acknowledges they must substantially a to the conditions that existed prior to the release or their final land use in the OCD when reclamation and re-vegetation are complete.
Printed Name: Thomas Long	Title: Senior Environmental Scientist
Signature:	Date: <u>05-23-2022</u>
email: tjlong@eprod.com	
OCD Only	
Received by:	Date:
	sible party of liability should their operations have failed to adequately investigate and r, surface water, human health, or the environment nor does not relieve the responsible laws and/or regulations.
Closure Approved by:	Date:
Printed Name:	Title:



ENTERPRISE PRODUCTS PARTNERS L.P. ENTERPRISE PRODUCTS HOLDINGS LLC (General Partner) **ENTERPRISE PRODUCTS OPERATING LLC** 

### Enterprise Field Services, LLC Lindrith Compressor Station Incident # nAPP2113437743

On May 14, 2021, at approximately 9:45 a.m., Enterprise had a release of condensate from an above ground storage tank at Lindrith Compressor Station. Approximately 80 barrels of condensate were released into a lined secondary containment. No liquids were observed outside of the secondary containment. No residences were affected. No emergency services responded. The tank was drained and removed from service in the fall of 2021 and subsequent weather events caused a buildup of snow and ice on the containment liner not allowing it to be inspected. The liner was inspected by Enterprise Field Services, LLC and Jicarilla Apache Environmental Protection Office representatives on May 3, 2022 and found no tears or punctures.



DATE: 05-04-2022 DRAWN BY: TJLONG DATE: 05-04-2022 CHECKED BY: BSTONE DATE: 05-04-2022 APPROVED BY: BSTONE

LINDRITHCS

PROJ. ID: SCALE: DRAWING NUMBER:

1"=60'

Released to Imaging: 3/7/2023 11:16:49 AM

# Enterprise Field Services, LLC Lindrith Compressor Station Incident #nAPP2113437743



Photo 1: View of the liner. View to the north.



Photo 2: View of the liner where Tank # 30 was removed. View to the north.

# Enterprise Field Services, LLC Lindrith Compressor Station Incident #nAPP2113437743




Photo 3: Another view of the liner where Tank # 30 was removed. View to the west.



Photo 4: Another view of the liner where Tank # 30 was removed. View to the east .

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 109403

#### **CONDITIONS**

Operator:	OGRID:
Enterprise Field Services, LLC	241602
PO Box 4324	Action Number:
Houston, TX 77210	109403
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By	Condition	Condition Date
nvelez	Closure accepted for the record based on Jicarilla EPO approval.	3/7/2023