

Liner Inspection and Closure Request

BTA Oil Producers, LLC
Harroun Ranch West
Eddy County, New Mexico
Unit Letter "P", Section 20, Township 23 South, Range 29 East
Latitude 32.285656 North, Longitude 104.006464 West
NMOCD Incident # nAPP2320551953

Prepared For:

BTA Oil Producers 104 S. Pecos St. Midland, TX 79701

Prepared By:

Hungry Horse, LLC 4024 Plains Hwy Lovington, NM 88260

Office: (575) 393-3386

August 2023

Bradley Wells
Project Manager
bwells@hungry-horse.com

Daniel Dominguez
Environmental Manager
ddominguez@hungry-horse.com

Table Of Contents

NMOCD Form C-141 Remediation and Closure Pages	
Background	1
NMOCD Site Classification	1
Liner Inspection	2
Closure Request	2
Limitations	2
Distribution	3

Figures

Figure 1 – Topographic Map
Figure 2 – OSE POD Locations Map
Figure 3 – USGS Well Locations Map

Figure 4 – Liner Inspection Map

Attachments

Attachment I – Karst and Wetland Maps

Attachment II – NMOCD Correspondence

Attachment III - Site Photographs

Attachment IV – Depth to Groundwater

Attachment V – Liner Inspection Report

Attachment VI – NMOCD Form Initial C-141

	Page 3 of 3	38
Incident ID	nAPP2320551953	
District RP		
Facility ID		
Application ID		

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<u><50'</u> (ft bgs)				
Did this release impact groundwater or surface water?	☐ Yes ⊠ No				
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ⊠ No				
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ⊠ No				
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ⊠ No				
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ⊠ No				
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ⊠ No				
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ⊠ No				
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ⊠ No				
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ⊠ No				
Are the lateral extents of the release overlying an unstable area such as karst geology?	⊠ Yes □ No				
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ⊠ No				
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ⊠ No				
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.					
Characterization Report Checklist: Each of the following items must be included in the report.					
 Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wel ☐ Field data ☐ Data table of soil contaminant concentration data ☐ Depth to water determination 	ls.				

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release

Boring or excavation logs

Topographic/Aerial maps

Photographs including date and GIS information

□ Laboratory data including chain of custody

Received by OCD: 8/22/2023 6:05:03 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 4 of	38
Incident ID	nAPP2320551953	
District RP		
Facility ID		

Application ID

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. **Kelton Beaird** Title: Environmental Manager Printed Name: Signature: Date: 8-22-23 Telephone: 432-312-2203 kbeaird@btaoil.com email: **OCD Only** Date: 8/22/2023 Received by: Shelly Wells

	Page 5 of	38
Incident ID	nAPP2320551953	
District RP		
Facility ID		
Application ID		

Remediation Plan

Remediation Plan Checklist: Each of the following items must be included in the	plan.		
 ☑ Detailed description of proposed remediation technique ☑ Scaled sitemap with GPS coordinates showing delineation points ☑ Estimated volume of material to be remediated ☑ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC ☑ Proposed schedule for remediation (note if remediation plan timeline is more than the content of the conte	nn 90 days OCD approval is required)		
Deferral Requests Only: Each of the following items must be confirmed as part of	of any request for deferral of remediation		
Deterral requests Only. Each of the following tiems must be confirmed as part of	y any request for deferral of remediation.		
Contamination must be in areas immediately under or around production equipmedeconstruction.	nent where remediation could cause a major facility		
Extents of contamination must be fully delineated.			
Contamination does not cause an imminent risk to human health, the environment	nt, or groundwater.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name: Kelton Beaird Title:	Environmental Manager		
Signature: Date: 8-22			
email: kbeaird@btaoil.com Telephone: _	432-312-2203		
OCD Only			
Received by: Shelly Wells Date: 8/22/202	23		
☐ Approved ☐ Approved with Attached Conditions of Approval ☐	☐ Denied ☐ Deferral Approved		
Signature: Date:			

Page 6 of 38

	1 180 0 0 1
Incident ID	nAPP2320551953
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following	items must be included in the closure report.
A scaled site and sampling diagram as described in 19.15.29	.11 NMAC
Photographs of the remediated site prior to backfill or photomust be notified 2 days prior to liner inspection)	os of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate OD	OC District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file certa may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and re human health or the environment. In addition, OCD acceptance of	lations. The responsible party acknowledges they must substantially conditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.
email: kbeaird@btaoil.com	Date: <u>8-22-23</u> Telephone: <u>432-312-2203</u>
eman	reteptione
OCD Only	
Received by: Shelly Wells	Date: <u>8/22/2023</u>
	y of liability should their operations have failed to adequately investigate and e water, human health, or the environment nor does not relieve the responsible d/or regulations.
Closure Approved by: Shelly Wells	Date: <u>9/13/2023</u>
Printed Name: Shelly Wells	Title: Environmental Specialist-Advanced

The following *Liner Inspection and Closure Request* serves as a condensed update on field activities undertaken at the afore referenced Site.

Background:

The site is located in Unit Letter P (SE/SE), Section 20, Township 23 South, Range 29 East, approximately six miles east of Loving, in Eddy County, New Mexico. The site is located on Bureau of Land Management land. Topographic Map, OSE POD Locations Map, and USGS Well Locations Map are included as Figure 1, Figure 2, and Figure 3, respectively.

The release occurred within a metal containment lined with poly liner; Latitude 32.285656 North, Longitude 104.006464 West. The Initial NMOCD Form C-141 indicated that on July 23, 2023 approximately 30 bbls of produced water were released due to a site glass breaking. A crew was dispatched to the site with a vacuum truck. The site glass was repaired and 30 bbls of fluid were recovered. Previously submitted pages of the NMOCD Form C-141 are available on the NMOCD Imaging System. NMOCD Form Initial C-141 is also included as Attachment VI.

NMOCD Site Classification:

A search of the New Mexico Office of the State Engineer (NMOSE) and United States Geological Survey (USGS) groundwater databases was completed in an effort to determine the horizontal distance to known water sources within a half mile radius of the Release Site. Approximate depth to groundwater was determined using maintained and published water well data. Karst mapping indicates the site is located in a Karst designated area. Karst and Wetland Maps are provided as Attachment I. Depth to groundwater information is provided as Attachment IV and the results are depicted on Figures 2 & 3.

No water wells were located within a half mile of the release area. Utilizing this information, the NMOCD Closure Criteria for the Site is depicted in the table below. However, due to the release being contained within a lined containment area and all fluid was recovered, a liner inspection was scheduled.

Depth to Groundwater	Constituent	Method	Limit
	Chloride	EPA 300.0 or SM4500 CLB	600 mg/kg
<50'	TPH (GRO + DRO + MRO)	EPA SW-846 Method 8015M Ext	100 mg/kg
	GRO + DRO	EPA SW-846 Method 8015M Ext	N/A
	BTEX	EPA SW-846 Methods 8021B or 8260B	50 mg/kg
	Benzene	EPA SW-846 Methods 8021B or 8260B	10 mg/kg



Liner Inspection:

The release of 30 bbls of produced water occurred on July 23, 2023, due to a site glass breaking. A crew with a vacuum truck were contacted to recover the fluids and the site glass was repaired. It was reported by field that 30 bbls were recovered from vacuum truck loading. The released did not leave the lined containment, hit pad, or go offsite. On August 14, 2023, Hungry Horse LLC notified NMOCD that a liner inspection would be conducted on August 17, 2023. Email correspondence is provided as Attachment II.

On August 17, 2023, Hungry Horse personnel arrived on location to inspect the liner. The liner and metal containment were thoroughly inspected form edge to edge, as well as around the tanks and process equipment installed on the liner itself. The liner was found to be in place, intact, with no visible, breaks, or tears. There was no evidence of the release escaping the metal containment area. A completed Liner Inspection Form is attached as Attachment V and Photographs are provided as Attachment III.

Closure Request:

The Liner Inspection and correspondence with NMOCD were conducted in accordance with applicable NMOCD Regulations.

Based upon the reported volume recovered from the release and a thorough liner inspection with photographs demonstrating an intact, untorn, unbroken liner with no evidence of release escaping containment, BTA Oil Producers LLC respectfully requests closure of the Harroun Ranch West location, incident nAPP2320551953.

Limitations:

Hungry Horse, LLC, has prepared this *Liner Inspection and Closure Request* to the best of its ability. No other warranty, expressed or implied, is made or intended. Hungry Horse has examined and relied upon documents referenced in the report and on oral statements made by certain individuals. Hungry Horse has not conducted an independent examination of the facts contained in referenced materials and statements. Hungry Horse has presumed the genuineness of these documents and statements and that the information provided therein is true and accurate. Hungry Horse notes that the facts and conditions referenced in this report may change over time, and the conclusions and recommendations set forth herein are applicable only to the facts and conditions as described at the time of this report.



Distribution:

BTA Oil Producers, LLC

104 S. Pecos St. Midland, TX 79701

New Mexico Energy, Minerals and Natural Resources Department

Oil Conservation Division, District 2 811 S. First St. Artesia, NM 88210

New Mexico Bureau of Land Management

620 E. Greene St Carlsbad, NM 88220

Figures

Checked: dd

8/16/23

Date:

GPS: 32.285656, -104.006464

Eddy County

Received by OCD: 8/22/2023 6:05:03 AM Page 12 of 38




Figure 2

OSE POD Locations Map BTA Oil Producers, LLC Harroun Ranch West GPS: 32.285656, -104.006464 Eddy County

Legend:

Harroun Ranch West Location

Drafted: bw Checked: dd Date: 8/16/23



Received by OCD: 8/22/2023 6:05:03 AM Page 13 of 38



Figure 3

USGS Well Locations Map BTA Oil Producers, LLC Harroun Ranch West GPS: 32.285656, -104.006464 Eddy County Legend:

Harroun Ranch West Location

Drafted: bw Checked: dd Date: 8/16/23





Figure 4


Liner Inspection Map BTA Oil Producers, LLC Harroun Ranch West GPS: 32.285656, -104.006464 **Eddy County**

Legend:

Release Within Lined Containment Area

Drafted: bw Checked: dd 8/16/23 Date:

Attachment I Karst and Wetland Maps



Harroun Ranch West

Karst springs

Spring with low

flow discharge ≥ 2 m³/s

Spring with low

- flow discharge < 2 m³/s
- Submarine spring
- Thermal spring

Water

- abstraction structure in karst aquifer
- Cave systems

Border between exposed and

- non-exposed karstifiable rocks
 - Selected city,
- partly dependent on groundwater
- Boundary of continuous permafrost
- Continuous ice sheet

Karstifiable rocks (potential karst aquifer)

Continuous carbonate rocks

Mercator Auxiliary Sphere
Projektion: Mercator Auxiliary Sphere

Discontinuous carbonate rocks

Continuous evaporite rocks

Discontinuous evaporite rocks


Mixed carbonate and evaporite rocks

Koordinatensystem: WGS 1984 Web Datum: WGS 1984

Exportdatum: 17.08.2023



Harroun Ranch West



August 21, 2023

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake

Riverine



Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Attachment II NMOCD Correspondence

Daniel Dominguez

From: Wells, Shelly, EMNRD <Shelly.Wells@emnrd.nm.gov>

Sent: Monday, August 14, 2023 2:43 PM

To: Daniel Dominguez

Cc: Bratcher, Michael, EMNRD; Hamlet, Robert, EMNRD

Subject: RE: [EXTERNAL] Liner Inspection

Hi Daniel,

The OCD has received your notification. Include a copy of this and all notifications in the remedial and/or closure reports to ensure the notifications are documented in the project file.

Thank you,

Shelly

Shelly Wells * Environmental Specialist-Advanced Environmental Bureau EMNRD-Oil Conservation Division 1220 S. St. Francis Drive|Santa Fe, NM 87505 (505)469-7520|Shelly.Wells@emnrd.nm.govhttp://www.emnrd.state.nm.us/OCD/

From: Daniel Dominguez <ddominguez@hungry-horse.com>

Sent: Monday, August 14, 2023 2:11 PM

To: Enviro, OCD, EMNRD < OCD. Enviro@emnrd.nm.gov>

Subject: [EXTERNAL] Liner Inspection

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

We will be conducting a liner inspection at the Harroun Ranch West (nAPP2320551953) on Thursday August 17, 2023 at 1 pm. This is our 2 day notice.


Daniel Dominguez
Environmental Manager
Hungry Horse, LLC
(mobile) 575-408-3134
ddominguez@hungry-horse.com

Attachment III Site Photographs

Photographs






















Photographs





Photographs














Attachment IV Depth to Groundwater



New Mexico Office of the State Engineer

Wells with Well Log Information

No wells found.

UTMNAD83 Radius Search (in meters):

Easting (X): 593554.71 **Northing (Y):** 35

Northing (Y): 3572532.54 **Radius:** 805

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for particular purpose of the data.

8/21/23 1:06 PM WELLS WITH WELL LOG INFORMATION

Attachment V Liner Inspection Report

Liner Inspection Form

Client	BTA Oil Producers, LLC				
Site Name	Harroun Ranch West				MAENTAL & CONSTRUCTION
Lat/Long	32.285656, -104.006	464			IN SECTION OF THE PROPERTY OF
Release Date	23-Jul-23				NTAL & CON
Incident Number	nAPP2320551953				
NMOCD Notified	14-Aug-23				
Inspection Date	8/17/23		+		
Observations		Yes	No	Con	nments
Is the liner present?		Х			
Is the liner torn?			Х		
Are there visible hol	es in the liner?		X	Sale:	
Is the liner retaining	any liquids?		X		
Does it appear the li	· ·	X			
to contain the leak?		~			
Type of liner:	Earthen with liner		Earthen n	o liner	
	Metal with Poly Linin	g	Metal witl	າ Spray Epoxy Lining	
	Other:				_ ,
Other concerns or o	bservations: Linea	$\sim \omega$	25 in	tacto No	Converns
	tions.				
				-	
Inspector Name	Bradley Wells				
Inspector Signature)
	- V				

Attachment VI NMOCD Form Initial C-141

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural** Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2320551953
District RP	
Facility ID	
Application ID	

Volume/Weight Recovered (provide units)

Release Notification

			Res	ponsi	ble Part	y		
Responsible Party: BTA Oil Producers, LLC			OGRID: 2	OGRID: 260297				
Contact Nan	ne: Kelton E	Beaird			Contact To	elephone: 432-3	312-2203	
Contact ema	il: kbeaird@	taoil.com			Incident #	(assigned by OCD)		
Contact mail	ling address:	104 S. Pecos St.	, Midland, TX 79	701				
			Location	n of R	Release S	ource		
Latitude: 32	.28575		(NAD 83 in a	lecimal de	Longitude:	-104.00646 nal places)		
Site Name: I	Harroun Ran	ch West			Site Type:	Production faci	ility	
Date Release	Discovered	7-23-2023			API# (if applicable)			
Unit Letter	Section	Township	Range		Cour	nty]	
P	20	23S	29E	Edd	Eddy			
Surface Owne	r: State	⊠ Federal □ T	ribal Private	(Name:)	
			Nature an	d Vo	lume of 1	Release		
Crude Oi				ch calcula	tions or specific		e volumes provided below)	
		Volume Release				Volume Recovered (bbls) 30		
Produced Water Volume Released (bbls)			Volume Recovered (bbls)					
		Is the concentrate produced water	tion of dissolved >10,000 mg/l?	chlorid	e in the	in the Yes No		
Condensa	ate	Volume Release				Volume Recovered (bbls)		
☐ Natural C	as	Volume Release	ed (Mcf)			Volume Recovered (Mcf)		

Volume/Weight Released (provide units)

Cause of Release A sight glass broke, releasing fluid inside the lined secondary containment.

Released to Imaging: 9/13/2023 3t86t02PMM

Other (describe)

Received by OCD: 8/22/2023 6:05:03 AMI State of New Mexico
Page 2 Oil Conservation Division

Page 36 of 38

Incident ID	NAPP2320551953
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release? Exceeded 25 bbls.				
19.15.29.7(A) NMAC?					
⊠ Yes □ No					
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? By Kelton Beaird to ocd.enviro, Mike Bratcher, Robert Hamlet on 7-24-2023 by email.					
	Initial Response				
The responsible p	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury				
☐ The source of the rele	ease has been stopped.				
☐ The impacted area ha	s been secured to protect human health and the environment.				
Released materials ha	we been contained via the use of berms or dikes, absorbent pads, or other containment devices.				
All free liquids and re	ecoverable materials have been removed and managed appropriately.				
If all the actions described	d above have not been undertaken, explain why:				
D 10 15 20 9 D (4) NM	AC the recognitive many commence remediation immediately after discovery of a release. If remediation				
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.					
regulations all operators are public health or the environr failed to adequately investig	rmation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger nent. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have attend remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In f a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws				
Printed Name: Kelton Be	eaird Title: Environmental Manager				
Signature:	Date: 7-28-2023				
email: kbeaird@btaoil.co	om Telephone: 432-312-2203				
OCD Only					
Received by: Shally Wal	ls Date: <u>7/31/2023</u>				
Received by: Sileny Wei	15				

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 245338

CONDITIONS

Operator:	OGRID:
BTA OIL PRODUCERS, LLC	260297
104 S Pecos	Action Number:
Midland, TX 79701	245338
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created B	y Condition	Condition Date
scwells	None	7/31/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 255170

CONDITIONS

Operator:	OGRID:
BTA OIL PRODUCERS, LLC	260297
104 S Pecos	Action Number:
Midland, TX 79701	255170
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created I	By Condition	Condition Date
scwell	None	9/13/2023