District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Page 1 of 11

Incident ID	nAPP2331132684
District RP	
Facility ID	
Application ID	

# **Release Notification**

## **Responsible Party**

Responsible Party DCP Operating Company, LP	OGRID 36785	
Contact Name: Nicholas L. Case	Contact Telephone 575-802-5225	
Contact email Nicholas.L.Case@p66.com	Incident # (assigned by OCD)	
Contact mailing address 5301 Sierra Vista Drive	Carlsbad, NM 88220	

### **Location of Release Source**

Latitude <u>32.643464</u>

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: G-P Permian	Site Type: Compressor
Date Release Discovered: 11/03/2023	API# (if applicable)

Unit Letter	Section	Township	Range	County
K	19	19S	32E	Lea

Surface Owner: State Federal Tribal Private (Name: BLM\_

## Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (bbls):	Volume Recovered (bbls):
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ⊠ No
Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (Mcf)	Volume Recovered (Mcf)
Volume/Weight Released (provide units)NA	Volume/Weight Recovered (provide units) NA
	Volume Released (bbls):         Is the concentration of dissolved chloride in the produced water >10,000 mg/l?         Volume Released (bbls)         Volume Released (Mcf)

Cause of Release:

On November 3, 2023, DCP Ops discovered a fire at C-5 inlet Compressor. While starting another engine, operations noticed a small fire starting on the valve cover on engine 1250. Operations ESD the engine and used fire extinguisher to extinguish fire. No injuries occurred from the incident.

Form C-141	
------------	--

Released to Imaging: 11/8/2023 11:42:55 AM

State of New Mexico Oil Conservation Division	Incident ID	nAPP2331132684
	District RP	
	Facility ID	
	Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the	responsible party consider this a major release?
Yes 🗌 No		
	notice given to the OCD? By whom? nber 3, 2023 at 12:21 pm from Nichola	To whom? When and by what means (phone, email, etc)? Via email to as Case with Phillips 66.
	Initia	al Response
The responsible	party must undertake the following actions imn	nediately unless they could create a safety hazard that would result in injury
The source of the rel	ease has been stopped.	
The impacted area ha	as been secured to protect human healt	th and the environment.
Released materials h	ave been contained via the use of bern	ns or dikes, absorbent pads, or other containment devices.
All free liquids and r	ecoverable materials have been remov	ed and managed appropriately.
If all the actions describe	ed above have <u>not</u> been undertaken, ex	plain why:
has begun, please attach	a narrative of actions to date. If rem	ence remediation immediately after discovery of a release. If remediation nedial efforts have been successfully completed or if the release occurred AC), please attach all information needed for closure evaluation.
		to the best of my knowledge and understand that pursuant to OCD rules and
public health or the environ failed to adequately investig	iment. The acceptance of a C-141 report b gate and remediate contamination that pose	ise notifications and perform corrective actions for releases which may endanger by the OCD does not relieve the operator of liability should their operations have e a threat to groundwater, surface water, human health or the environment. In ator of responsibility for compliance with any other federal, state, or local laws
Printed Name: Nicholas	I. Case	Title: Environmental Specialist
Signature: <u>Hunflow</u>	L. Case	
Signature:	Date: 2023.11.07.1001-44-07.00	Date:
email: Nicholas.L.Case@	<u>vp66.com</u>	Telephone: 575-802-5225
OCD Only		
Received by: <u>Shelly V</u>	Wells	Date: <u>11/8/2023</u>
	7	

Form C-141

Page 6

Released to Imaging: 11/8/2023 11:42:55 AM

State of New Mexico **Oil Conservation Division** 

Incident ID	nAPP2331132684
District RP	
Facility ID	
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC

Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Date:

Printed Name: Nicholas L. Case 

Signature:

email: Nicholas.L.Case@p66.com

**OCD Only** 

Received by: Shelly Wells

Date: 11/8/2023

11/7/2023

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:	Shelly	Wells
----------------------	--------	-------

Date: 11/8/2023

Printed Name: Shelly Wells

Title: Environmental Specialist-Advanced

Title: Environmental Specialist

Telephone: 575-802-5225

### Kyle Norman

From: Sent:	Case, Nicholas L <nicholas.l.case@p66.com> Friday, November 3, 2023 12:21 PM</nicholas.l.case@p66.com>
То:	Michael Bratcher; Mike Bratcher
Cc:	Cook, John W; Millican, Scot A; Daly, Stacey; Smalts, Raymond A; Acosta, Jonathan; Kyle Norman; Brett Dennis; Brown, Clint; Hargrove, Javier; Boswell, Jordan B; Lathram, Shelbi R; Case, Nicholas L
Subject:	Small incipient fire/ Zia2 GP Lea County
Follow Up Flag:	Follow up
Flag Status:	Flagged

Mr. Bratcher: I was notified of small fire that occurred this morning (11/03/2023) at the Zia2 Gas Plant in Lea County (32.643464 -103.808534). The fire was in the incipient stage and was extinguished by operations. There were no injuries, Emergency Services were not notified, there was very little damage (to the 1250 or C5-E inlet Compressor), and there are no emissions calculable for this event.

#### Therefore;

In an abundance of caution and to meet potentially applicable reporting deadlines, DCP is submitting this initial report based on the information currently available and DCP's understanding of the facts at this time; however, DCP's investigation and assessment is ongoing. DCP therefore reserves the right to supplement and revise the information in this initial report if and as new information becomes available. DCP also reserves the right to raise any arguments, facts, or defenses regarding this incident, including that this incident is not a "major release" as defined by 19.15.29.7(A) NMAC.

Please contact me if you have any additional questions or concerns for this possible NOR.

Thank you Nick

Nicholas L. Case Environmental Specialist SENM Asset M: 575-802-5225 5301 Sierra Vista Drive | Carlsbad, NM 88220 phillips66.com Follow us: Twitter | Facebook | LinkedIn | Instagram



### Kyle Norman

From:	Case, Nicholas L <nicholas.l.case@p66.com></nicholas.l.case@p66.com>
Sent:	Monday, November 6, 2023 4:55 PM
То:	Brett Dennis; Kyle Norman
Subject:	FW: Incident Reported - Event # 2983830

From: SpheraCloud <noreplySC@sphera.com>
Sent: Monday, November 6, 2023 10:30 AM
To: GRP:Midstream/Lubes - HSE - All <MidstreamLubesHSEAll@p66.com>
Subject: Incident Reported - Event # 2983830

# **Incident Reported**

The following Event has been reported.

To view/update the Event, please log into <u>SpheraCloud (auto login)</u> or <u>SpheraCloud (manual login)</u> and navigate to the 'Events' tab.

#### 🛃 Event Details

**ID:** 2983830 <u>View event</u> Location: Zia II Plant Site Name: G-P Permian Type: Incident **Consequences:** Title: Engine 1250 Flash fire Description: while starting another engine, operations notices a small fire starting on the valve cover on engine 1250. Operations ESD the engine and use fire extinguisher to extinguished fire. Date Reported: 03 November 2023 Reported By: Jonathan Acosta Date Occurred: 03 November 2023 Time occurred: 09:30 Immediate Actions Taken: operations ESD engine and used fire extinguisher to extinguished fire. Then they reported it to proper personnel. Owner: Javier Hargrove Current Status: Draft Workflow Notes:

Powered by **SpheraCloud** 


Included on this email (To):

midstreamprojects@p66.com, travis.k.hager@p66.com, midstreamlubeshseall@p66.com, amy.d.gross@p66.com, midstreamtechnologyoperationalservicesall@p66.com, javier.j.becerra@p66.com, ralph.herrera@p66.com, al.veronie@contractor.p66.com, andrew.s.cole@p66.com, midstreamspheraimpactgpsouth@p66.com, stephanie.d.wilson@p66.com, catherine.s.turlington@p66.com, jim.d.wolf@p66.com, thuy.h.tran@p66.com, denee.cartwright@p66.com















#### **Received by OCD: 11/8/2023 5:59:26 AM**

.



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DCP OPERATING COMPANY, LP	36785
6900 E. Layton Ave	Action Number:
Denver, CO 80237	283732
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By Condition scwells None

CONDITIONS

Action 283732

Condition Date

11/8/2023