



AKM MEASUREMENT SERVICES,LLC. Natural Gas Analysis Report
GPA 2172-09/API 14.5 Report with GPA 2145-16 Physical Properties

| Sample Information | |
|----------------------------------|--------------------------------------|
| Sample Name | CYPRESS 33 B 2 CDP |
| Technician | ANTHONY DOMINGUEZ |
| Analyzer Make & Model | INFICON MICRO GC |
| Last Calibration/Validation Date | 10-05-2023 |
| Meter Number | 2.10.12 |
| Air temperature | 85 |
| Flow Rate (MCF/Day) | 7285 |
| Heat Tracing | HEATED HOSE & GASIFIER |
| Sample description/mtr name | CYPRESS 33 B 2 CDP |
| Sampling Method | FILL & EMPTY |
| Operator | OCCIDENTAL PETROLEUM, OXY USA INC |
| State | NEW MEXICO |
| Region Name | PERMIAN_RESOURCES |
| Asset | NEW MEXICO |
| System | EAST OF PECOS |
| FLOC | OP-L3818-BT002 |
| Sample Sub Type | CDP |
| Sample Name Type | METER |
| Vendor | AKM MEASUREMENT |
| Cylinder # | 38939 |
| Sampled by | CHANDLER MONTGOMERY |
| Sample date | 10-4-2023 |
| Analyzed date | 10-7-2023 |
| Method Name | C9 |
| Injection Date | 2023-10-07 14:42:16 |
| Report Date | 2023-10-07 14:44:06 |
| EZReporter Configuration File | 1-16-2023 OXY GPA C9+ H2S #2.cfgx |
| Source Data File | 74044316-76a2-4312-a506-52728f84dc9e |
| NGA Phys. Property Data Source | GPA Standard 2145-16 (FPS) |
| Data Source | INFICON Fusion Connector |

Component Results

| Component Name | Peak Area | Raw Amount | Response Factor | Norm Mole% | Gross HV (Dry) (BTU / Ideal cu.ft.) | Relative Gas Density (Dry) | GPM (Dry) (Gal. / 1000 cu.ft.) |
|----------------|-----------|------------|-----------------|------------|-------------------------------------|----------------------------|--------------------------------|
| Nitrogen | 15458.9 | 0.8783 | 0.00005681 | 0.8770 | 0.0 | 0.00848 | 0.097 |
| Methane | 1074930.3 | 79.0359 | 0.00007353 | 78.9197 | 798.9 | 0.43714 | 13.429 |
| CO2 | 2698.1 | 0.1289 | 0.00004778 | 0.1287 | 0.0 | 0.00196 | 0.022 |
| Ethane | 233286.9 | 10.7010 | 0.00004587 | 10.6852 | 189.5 | 0.11093 | 2.868 |
| H2S | 0.0 | 0.0000 | 0.00000000 | 0.0000 | 0.0 | 0.00000 | 0.000 |
| Propane | 144721.3 | 4.5768 | 0.00003162 | 4.5701 | 115.3 | 0.06958 | 1.264 |
| iso-butane | 65229.3 | 0.7352 | 0.00001127 | 0.7341 | 23.9 | 0.01473 | 0.241 |
| n-Butane | 148022.1 | 1.6546 | 0.00001118 | 1.6521 | 54.0 | 0.03315 | 0.523 |
| iso-pentane | 46360.1 | 0.4574 | 0.00000987 | 0.4567 | 18.3 | 0.01138 | 0.168 |
| n-Pentane | 56474.8 | 0.5450 | 0.00000965 | 0.5442 | 21.9 | 0.01356 | 0.198 |
| hexanes | 63582.0 | 0.4908 | 0.00000772 | 0.4901 | 23.4 | 0.01458 | 0.202 |
| heptanes | 72201.0 | 0.5237 | 0.00000725 | 0.5229 | 28.8 | 0.01809 | 0.242 |
| octanes | 45884.0 | 0.3410 | 0.00000743 | 0.3405 | 21.3 | 0.01343 | 0.175 |
| nonanes+ | 6371.0 | 0.0788 | 0.00001237 | 0.0787 | 5.5 | 0.00349 | 0.044 |
| Total: | | 100.1473 | | 100.0000 | 1300.9 | 0.75049 | 19.474 |

Results Summary

| Result | Dry | Sat. |
|---------------------------|----------|------|
| Total Un-Normalized Mole% | 100.1473 | |
| Pressure Base (psia) | 14.730 | |
| Temperature Base (Deg. F) | 60.00 | |
| Relative Humidity (%) | 93.5 | |

| Result | Dry | Sat. |
|--|--------|--------|
| Flowing Pressure (psia) | 51.6 | |
| Gross Heating Value (BTU / Ideal cu.ft.) | 1300.9 | 1278.3 |
| Gross Heating Value (BTU / Real cu.ft.) | 1306.1 | 1283.9 |
| Relative Density (G), Real | 0.7532 | 0.7512 |

Monitored Parameter Report

| Parameter | Value | Lower Limit | Upper Limit | Status |
|----------------------------|----------|-------------|-------------|--------|
| Total un-normalized amount | 100.1473 | 97.0000 | 103.0000 | Pass |

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Cypress 33B CTB**Flare Date:** 08/29/2024**Duration of Event:** 3 Hours 49 Minutes**MCF Flared:** 293**Start Time:** 11:00 AM**End Time:** 02:49 PM**Cause:** Emergency Flare > Third Party Downstream Activity > Targa > Equipment Issues**Method of Flared Gas Measurement:** Gas Flare Meter**1. Reason why this event was beyond Operator's control:**

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction, or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted Oxy's ability to send gas to them. This interruption, restriction, or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this event occurred with no advance notice or warning.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this flaring event occurred with no advance notice or warning. Oxy's operations were running in normal operations until Targa had issues on their end. As soon as flaring was triggered, the well optimizer adjusted injection rates and Oxy field personnel choked back all wells to help minimize and mitigate emissions. This event is out of OXY's control, yet OXY made every effort to control and minimize emissions as much as possible.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is unable to take any corrective actions to eliminate the cause and potential reoccurrence of a downstream third-party owned and operated sales line issue, as this is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid, prevent from happening or reoccur. When Targa has equipment issues, unplanned maintenance issues or greatly struggles to handle the volume of gas being sent to them by Oxy, Targa then restricts Oxy's ability to send its gas, which then prompts Oxy to route all its stranded gas not pushed into the Targa sales gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to continually communicate with Targa personnel, who own and operate the sales gas pipeline, when possible, during these types of circumstances.

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 383610

DEFINITIONS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 383610 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 383610

QUESTIONS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 383610 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| | |
|---|----------------------------------|
| Prerequisites | |
| <i>Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.</i> | |
| Incident Well | Unavailable. |
| Incident Facility | [fAPP2306227737] Cypress 33B CTB |

| | |
|---|---|
| Determination of Reporting Requirements | |
| <i>Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.</i> | |
| Was this vent or flare caused by an emergency or malfunction | Yes |
| Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event | No |
| Is this considered a submission for a vent or flare event | Yes, minor venting and/or flaring of natural gas. |
| <i>An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.</i> | |
| Was there at least 50 MCF of natural gas vented and/or flared during this event | Yes |
| Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water | No |
| Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence | No |

| | |
|---|--|
| Equipment Involved | |
| Primary Equipment Involved | Other (Specify) |
| Additional details for Equipment Involved. Please specify | Emergency Flare > Third Party Downstream Activity > Targa > Equipment Issues |

| | |
|--|---------------|
| Representative Compositional Analysis of Vented or Flared Natural Gas | |
| <i>Please provide the mole percent for the percentage questions in this group.</i> | |
| Methane (CH4) percentage | 79 |
| Nitrogen (N2) percentage, if greater than one percent | 1 |
| Hydrogen Sulfide (H2S) PPM, rounded up | 0 |
| Carbon Dioxide (CO2) percentage, if greater than one percent | 0 |
| Oxygen (O2) percentage, if greater than one percent | 0 |
| <i>If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.</i> | |
| Methane (CH4) percentage quality requirement | Not answered. |
| Nitrogen (N2) percentage quality requirement | Not answered. |
| Hydrogen Sulfide (H2S) PPM quality requirement | Not answered. |
| Carbon Dioxide (CO2) percentage quality requirement | Not answered. |
| Oxygen (O2) percentage quality requirement | Not answered. |

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 383610

QUESTIONS (continued)

| | |
|--|---|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 383610 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

QUESTIONS

| Date(s) and Time(s) | |
|--|------------|
| Date vent or flare was discovered or commenced | 08/29/2024 |
| Time vent or flare was discovered or commenced | 11:00 AM |
| Time vent or flare was terminated | 02:49 PM |
| Cumulative hours during this event | 4 |

| Measured or Estimated Volume of Vented or Flared Natural Gas | |
|---|---|
| Natural Gas Vented (Mcf) Details | Not answered. |
| Natural Gas Flared (Mcf) Details | Cause: Other Other (Specify) Natural Gas Flared Released: 293 Mcf Recovered: 0 Mcf Lost: 293 Mcf. |
| Other Released Details | Not answered. |
| Additional details for Measured or Estimated Volume(s). Please specify | Gas Flare Meter |
| Is this a gas only submission (i.e. only significant Mcf values reported) | Yes, according to supplied volumes this appears to be a "gas only" report. |

| Venting or Flaring Resulting from Downstream Activity | |
|---|--------------------------------------|
| Was this vent or flare a result of downstream activity | Yes |
| Was notification of downstream activity received by this operator | No |
| Downstream OGRID that should have notified this operator | [24650] TARGA MIDSTREAM SERVICES LLC |
| Date notified of downstream activity requiring this vent or flare | Not answered. |
| Time notified of downstream activity requiring this vent or flare | Not answered. |

| Steps and Actions to Prevent Waste | |
|--|--|
| For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control. | True |
| Please explain reason for why this event was beyond this operator's control | The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction, or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted Oxy's ability to send gas to them. This interruption, restriction, or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this event occurred with no advance notice or warning. |
| Steps taken to limit the duration and magnitude of vent or flare | It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this |

| | |
|--|--|
| | <p>flaring event occurred with no advance notice or warning. Oxy's operations were running in normal operations until Targa had issues on their end. As soon as flaring was triggered, the well optimizer adjusted injection rates and Oxy field personnel choked back all wells to help minimize and mitigate emissions. This event is out of OXY's control, yet OXY made every effort to control and minimize emissions as much as possible.</p> |
| <p>Corrective actions taken to eliminate the cause and reoccurrence of vent or flare</p> | <p>Oxy is unable to take any corrective actions to eliminate the cause and potential reoccurrence of a downstream third-party owned and operated sales line issue, as this is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid, prevent from happening or reoccur. When Targa has equipment issues, unplanned maintenance issues or greatly struggles to handle the volume of gas being sent to them by Oxy, Targa then restricts Oxy's ability to send its gas, which then prompts Oxy to route all its stranded gas not pushed into the Targa sales gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to continually communicate with Targa personnel, who own and operate the sales gas pipeline, when possible, during these types of circumstances.</p> |

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720
District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720
District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 383610

ACKNOWLEDGMENTS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 383610 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

ACKNOWLEDGMENTS

| | |
|-------------------------------------|---|
| <input checked="" type="checkbox"/> | I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC. |
| <input checked="" type="checkbox"/> | I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively. |
| <input checked="" type="checkbox"/> | I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act. |
| <input checked="" type="checkbox"/> | I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment. |
| <input checked="" type="checkbox"/> | I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations. |

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 383610

CONDITIONS

| | |
|--|--|
| Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294 | OGRID: 16696 |
| | Action Number: 383610 |
| | Action Type: [C-129] Venting and/or Flaring (C-129) |

CONDITIONS

| Created By | Condition | Condition Date |
|---------------|--|----------------|
| shelbyschoepf | If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event. | 9/13/2024 |